

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010751/EVY3N2**Date:** 24/11/2021REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00104142101
Claimant Vehicle No : GBE7098Y **Insured Vehicle No :** XE2647K
 Date of Loss: 16/10/2021 Nature of Claim: TP Claim No: SNM21D205947/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBE7098Y**
 Make & Model: RENAULT KANGOO II, 1.6 D EXPRESS AT ABS AB 2WD 6DR (M) Engine No: K9KB608D608438
 Reg. Date: 03/03/2016 (Man. Year: 2015) Chassis No: VF1FW18H554200438
 Colour: White Odometer: 160118 km
 Engine Capacity: 1461 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
 Front Left Side: Yokohama 4 mm Rear Left Side: Yokohama 4 mm
 Front Right Side: Yokohama 4 mm Rear Right Side: Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,308.20	7,543.10	8,765.10	53.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,670.00	1,090.00	1,580.00	59.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,978.20	8,633.10	10,345.10	54.51
Approved Total (Overridden) (S\$)		6,750.00		
(S\$)	18,978.20	6,750.00	12,228.20	64.43
+ GST 7.00/7.00% (S\$)	1,328.47	472.50	855.97	64.43
Nett Amount (S\$)	20,306.67	7,222.50	13,084.17	64.43

INSPECTION

Date of Assignment: 19/10/2021
 Date Inspected: 25/10/2021 Inspected At: Wah Hong Motors & Credit Pte Ltd (HQ)
 38 Toh Guan Road East, #01-57, Enterprise Hub
 Singapore 608581
 Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 24 Nov 2021)

Parts: N/A RENAULT KANGOO II 1.6 D EXPRESS AT ABS AB 2WD 6DR (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBE7098Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID DOOR LH	Dented	1,900.00 FL	*1,900.00 FL
2	1		*BOOT LID DOOR EMBLEM KANGOO	Necessary	256.00 FL	*80.00 FL
3	1		*BOOT LID DOOR EMBLEM MAXI	Necessary	256.00 FL	*80.00 FL
4	1		*BOOT LID DOOR RH EMBLEM RENAULT	Necessary	276.00 FL	*110.00 FL
5	1		*BOOT LID DOOR RH	Dented	2,090.00 FL	*1,994.00 FL
6	1		*REAR BUMPER	Not Necessary	1,100.00 FL	*- FL
7	2		*REAR BUMPER SIDE BRACKET LH/RH	Not Necessary	360.00 FL	*- FL
8	1		*REAR BUMPER CENTER BRACKET	Not Necessary	300.00 FL	*- FL
9	1		*REAR REINFORCEMENT	Not Necessary	440.00 FL	*- FL
10	1		*END PANEL	Not Necessary	1,080.00 FL	*- FL
11	1		*FRONT BUMPER	Broken	1,330.00 FL	*895.00 FL
12	1		*FRONT SUPPORT FRONT GARNISH	Broken	1,330.00 FL	*520.00 FL
13	1		*FRONT BUMPER TOWING COVER	Missing	170.00 FL	*140.00 FL
14	1		*CENTER GRILLE BASE	Crushed	170.00 FL	*170.00 FL
15	1		*CENTER GRILLE TOP GARNISH	Cut	460.00 FL	*330.00 FL
16	2		*CENTER GRILLE CENTER SIDE GARNISH LH/RH	Not Necessary	380.00 FL	*- FL
17	1		*CENTER GRILLE LOWER GARNISH	Cut	250.00 FL	*250.00 FL
18	1		*CONDENSER	Not Necessary	900.00 FL	*- FL
19	1		*RADIATOR	Not Necessary	840.00 FL	*- FL
20	1		*FAN COWLING	Not Necessary	560.00 FL	*- FL
21	1		*FRONT REINFORCEMENT	Dented	680.00 FL	*480.00 FL
22	2		*FRONT BUMPER SIDE BRACKET LH/RH	Not Necessary	360.00 FL	*- FL
23	2		*HEADLAMP LH/RH	Broken	1,160.00 FL	*1,160.00 FL
24	1		*FRONT SUPPORT TOP PANEL	Not Necessary	800.00 FL	*- FL
25	1		*REAR BUMPER CLIPS	Necessary	35.00 FS	*30.00 FS
26	1		*REAR CAR PLATE WITH HOLDER	Cut	35.00 FS	*30.00 FS
27	1		*REAR REVERSE SENSOR	Not Necessary	200.00 FS	*- FS
28	1		*END PANEL SEALANT	Not Necessary	50.00 FS	*- FS
29	1		*BOOT LID DOOR LH WINDSCREEN SEALANT	Necessary	50.00 FS	*30.00 FS
30	1		*BOOT LID DOOR RH WINDSCREEN SEALANT	Necessary	50.00 FS	*30.00 FS
31	1		*70KM/H STICKER	Necessary	20.00 FS	*20.00 FS
32	1		*5PAX STICKER	Necessary	20.00 FS	*20.00 FS
33	1		*FRONT CAR PLATE WITH HOLDER	Broken	35.00 FS	*35.00 FS
34	1		*COOLANT	Not Necessary	50.00 FS	*- FS
35	1		*FRONT BUMPER CLIPS	Necessary	35.00 FS	*30.00 FS
36	1		*CENTER GRILLE CLIPS	Necessary	25.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,053.00	8,354.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,744.80	810.90
Total Parts (\$\$)	16,308.20	7,543.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS;PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	1,000.00	500.00
2	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	1,000.00	400.00
3	TO REMOVE AND REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL PROPER FUNCTION	New	90.00	30.00
4	TO REMOVE,REPLACE AND FOCUS HEADLAMP BEAM	New	60.00	30.00
5	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	60.00	30.00
6	TO REMOVE AND REFIT/REPLACE REAR COMPARTMENT FITTING,TRIMMINGS,GARNISH AND ETC	New	100.00	0.00
7	TO REMOVE AND REPLACE REAR REVERSE SENSOR	New	60.00	0.00
8	TO REMOVE AND REFIT/REPLACE REAR BOOTLID DOOR LH FITTING,TRIMMINGS,GARNISH,WINDOW GLASS AND LOCK MECHANISM	New	100.00	50.00
9	TO REMOVE AND REFIT AIRCON CONDENSER,RADIATOR,RELATED PIPES AND HOSES,VACCUM AND REFILL AIRCON GAS	New	100.00	0.00
10	TO REMOVE AND REFIT/REPLACE REAR BOOTLID DOOR RH FITTING,TRIMMINGS,GARNISH,WINDOW GLASS AND LOCK MECHANISM	New	100.00	50.00
Gross Labour Cost (S\$)			2,670.00	1,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >