

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21010759/UGS3Q2**Date:** 17/01/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : FBP8806G **Insured Vehicle No :** SLP6970J
 Date of Loss: 15/10/2021 Nature of Claim: TP Claim No: MFL2021D0004555

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBP8806G**
 Make & Model: YAMAHA GDR155A (AEROX), 155cc Engine No: G3J8E0091316
 Reg. Date: 27/06/2019 (Man. Year: 2019) Chassis No: MH3SG4640KJ050261
 Colour: Red Odometer: 9106 km
 Engine Capacity: 155 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/80-14 Rear Tyre Size: 140/70-14
 Front Left Side: IRC 7 mm Rear Left Side: IRC 7 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,273.30	2,555.30	3,718.00	59.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	590.00	310.00	280.00	47.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,863.30	2,865.30	3,998.00	58.25
Approved Total (Overridden) (S\$)		2,200.00		
Nett Amount (S\$)	6,863.30	2,200.00	4,663.30	67.95
+ Loss of Use (6.0 x S\$20.00/day) (S\$)		120.00		
Nett Liability (S\$)		2,320.00		

INSPECTION

Date of Assignment: 19/10/2021
 Date Inspected: 20/10/2021 Inspected At: Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)
 1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Dec 2021)	
Parts:	N/A	YAMAHA GDR155A (AEROX) 155cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBP8806G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FORK ASSY	Serviceable	980.00 FL	*- FL
2	1		*FORK UNDER BRACKET	Serviceable	190.00 FL	*- FL
3	1		*FRONT SPORT RIM	Not Necessary	550.00 FL	*- FL
4	1		*FRONT BRAKE DISC	Not Necessary	180.00 FL	*- FL
5	1		*FRONT RIM SHAFT	Cut	52.00 FL	*52.00 FL
6	1		*FRONT RIM BEARING	Not Necessary	48.00 FL	*- FL
7	1		*HEADLAMP	Cracked	550.00 FL	*499.00 FL
8	1		*FRONT SIGNAL	Cracked	150.00 FL	*105.00 FL
9	1		*SET SIDE MIRROR	Not Necessary	120.00 FL	*- FL
10	1		*HANDLE -BAR	Not Necessary	135.00 FL	*- FL
11	1		*SET HANDLE -BAR BALANCER	Not Necessary	80.00 FL	*- FL
12	1		*SET HAND GRIP	Not Necessary	60.00 FL	*- FL
13	1		*BRAKE LEVER	N/S Cut / O/S Not Necessary	104.00 FL	*38.00 FL
14	1		*FRONT SIDE COWLING -MATT	Cracked	150.00 FL	*105.00 FL
15	1		*FRONT SIDE INNER COWLING (N/S)	Cracked	180.00 FL	*148.00 FL
16	1		*FOOTSTEP PANEL	Cut	255.00 FL	*155.00 FL
17	1		*FOOTSTEP PANEL LOWER COVER	Cut	170.00 FL	*125.00 FL
18	1		*SIDE STAND	Not Necessary	108.00 FL	*- FL
19	1		*MAIN STAND	Cut	165.00 FL	*165.00 FL
20	1		*SET FAIRING COVER	Cracked	1,350.00 FL	*850.00 FL
21	1		*BELT COVER	Cut	175.00 FL	*175.00 FL
22	1		*AIR FILTER COVER	Not Necessary	125.00 FL	*- FL
23	1		*SET NUMBER PLATE	FRT Bent	38.00 FS	*10.00 FS
24	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
25	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
26	1		*SET STEERING CONE	Not Necessary	120.00 FS	*- FS
27	1		*REAR BOX	Cut	380.00 FS	*250.00 FS
28	1		*REAR BOX BRACKET	Not Necessary	180.00 FS	*- FS
29	1		*SET STICKER	Necessary	120.00 FS	*60.00 FS
30	1		*AEROX EMBLEM	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,861.00	2,797.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	587.70	241.70
Total Parts (\$\$)	6,273.30	2,555.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING (LOD)	New	60.00	60.00
2	TO PROVIDE WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	450.00	250.00
Gross Labour Cost (\$)			590.00	310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >