

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21010766/KPA3Q2**Date:** 16/12/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900161617
Claimant Vehicle No :	SKS4185T	Insured Vehicle No :	SMP4076S
Date of Loss:	05/10/2021	Nature of Claim:	TP
		Claim No:	9123074546SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS4185T	Engine No:	CZC225793
Make & Model:	AUDI A3, 1.4 SEDAN TFSI (AMBIENTE) (A)	Chassis No:	WAUZZZ8V6F1075190
Reg. Date:	14/04/2015 (Man. Year: 2014)	Odometer:	75183 km
Colour:	Metallic Black		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Dunlop 8 mm	Rear Left Side:	Dunlop 8 mm
Front Right Side:	Dunlop 8 mm	Rear Right Side:	Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,532.85	3,432.28	1,100.57	24.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,110.00	860.00	250.00	22.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,642.85	4,292.28	1,350.57	23.93
Approved Total (Overridden) (S\$)		3,400.00		
(S\$)	5,642.85	3,400.00	2,242.85	39.75
+ GST 7.00/7.00% (S\$)	395.00	238.00	157.00	39.75
Nett Amount (S\$)	6,037.85	3,638.00	2,399.85	39.75
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,145.45		
Global Sum Settlement (S\$)		4,100.00		

INSPECTION

Date of Assignment:	19/10/2021	Lim Tan Motor Pte Ltd (HQ)
Date Inspected:	25/10/2021 Inspected At:	Blk 176 Sin Ming Drive #03-09/10, Sin Ming Auto Care
Estimated Period of Repair:	4.0 days	Singapore 575721

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	1,514.50 FL	*1,514.50 FL
2	1		*FRONT BUMPER RETAINER	Distorted	27.00 FL	*27.00 FL
3	1		*FRONT BUMPER REINFORCEMENT	Repair	522.65 FL	*- FL
4	1		*FRONT BUMPER FOG LAMP COVER	Missing	79.55 FL	*79.55 FL
5	1		*FRONT BUMPER SPRAY NOZZLE COVER	Serviceable	41.10 FL	*- FL
6	1		*O/S HEADLAMP	Cut	1,559.85 FL	*1,559.85 FL
7	1		*HEAD LIGHT BULB	Serviceable	500.45 FL	*- FL
8	1		*O/S HEADLAMP SPRAY NOZZLE	Serviceable	158.65 FL	*- FL
9	1		*O/S FRONT FENDER	Buckled / Bent	632.75 FL	*632.75 FL
					Sub Total (\$)	5,036.50 3,813.65
					- List Item Discount on L Items 10.00/10.00% (\$)	503.65 381.37
					Total Parts (\$)	4,532.85 3,432.28

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PUTTY AND SPRAY PAINT	New	600.00	440.00
2	TO CHECK FRONT WIRING & FOCUS HEADLIGHTS	New	30.00	20.00
3	LABOUR CHARGES	New	480.00	400.00
Gross Labour Cost (\$)			1,110.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >