

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21010768/AVCE2**Date:** 03/01/2022**REFERENCE**

Insured/Claimant:	TAN JIAYING	Policy No:	2070103377	
Date of Loss:	11/10/2021	Nature of Claim:	OD	Claim No: 1817877764SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMT9488H</b>		
Make & Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Engine No:	CVK087158
Reg. Date:	24/07/2020 (Man. Year: 2019)	Chassis No:	WAUZZZF43KA111633
Colour:	Red	Odometer:	24379 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$140,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	24,674.00	3,059.12	21,614.88	87.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,622.00	2,272.00	6,350.00	73.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>33,296.00</b>	<b>5,331.12</b>	<b>27,964.88</b>	<b>83.99</b>
<b>- Excess (\$\$)</b>	<b>1,100.00</b>	<b>1,100.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(\$\$)</b>	<b>32,196.00</b>	<b>4,231.12</b>	<b>27,964.88</b>	<b>86.86</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>2,253.72</b>	<b>296.18</b>	<b>1,957.54</b>	<b>86.86</b>
<b>Nett Amount (\$\$)</b>	<b>34,449.72</b>	<b>4,527.30</b>	<b>29,922.42</b>	<b>86.86</b>

**INSPECTION**

Date of Assignment:	20/10/2021	
Date Inspected:	19/10/2021	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days	

**Adjuster:** ADRIAN LING**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,787.00 FS	*1,429.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	587.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	142.00 FS	*- FS
4	1		*FRONT BUMPER CENTER GRILLE	Cracked	196.00 FS	*156.40 FS
5	1		*FRONT BUMPER CLOSING ELEMENT	Cracked	210.00 FS	*167.60 FS
6	2		*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	126.00 FS	*- FS
7	1		*FRONT RADIATOR GRILLE	Cracked	1,332.00 FS	*1,065.60 FS
8	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	270.00 FS	*- FS
9	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	124.00 FS	*99.20 FS
10	1		*FRONT BUMPER REINFORCEMENT BAR	Not Necessary	845.00 FS	*- FS
11	1		*FRONT BUMPER TOP COVER	Not Necessary	127.00 FS	*- FS
12	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
13	1		*AIR-CONDITIONER STICKER	Not Necessary	8.00 FS	*- FS
14	1		*FRONT BUMPER REINFORCEMENT BRACKET	Not Necessary	137.00 FS	*- FS
15	2		*FRONT BUMPER REINFORCEMENT SUPPORT - LH / RH	Not Necessary	58.00 FS	*- FS
16	2		*FRONT PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
17	4		*FRONT PARKING AID SENSOR SEAL	Not Necessary	9.00 FS	*- FS
18	2		*HORN - LH / RH	Not Necessary	252.00 FS	*- FS
19	2		*HORN BRACKET - LH / RH	Not Necessary	58.00 FS	*- FS
20	2		*FRONT HEADLIGHT - LH / RH	Not Necessary	15,386.00 FS	*- FS
21	2		*FRONT HEADLIGHT LIFT CYLINDER - LH / RH	Not Necessary	420.00 FS	*- FS
22	1		*FRONT CORRUGATED PIPE	Not Necessary	93.00 FS	*- FS
23	1		*LOCK CARRIER SUPPORT PANEL	Not Necessary	1,016.00 FS	*- FS
24	2		*FRONT COOLANT SUPPORT	Not Necessary	76.00 FS	*- FS
25	1		*TEMPERATURE SENSOR BRACKET	Not Necessary	19.00 FS	*- FS
26	1		*INTERCOOLER	Not Necessary	587.00 FS	*- FS
27	6		*COOLANT	Not Necessary	266.00 FS	*- FS
28	1		*FRONT RADIATOR AIR GUIDE - OUTER LH / RH	N/S Torn	56.00 FS	*22.32 FS
29	2		*FRONT RADIATOR AIR GUIDE - INNER LH / RH	Not Necessary	24.00 FS	*- FS
30	1		*FRONT RADIATOR AIR GUIDE - UPPER	Not Necessary	16.00 FS	*- FS
31	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
32	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
33	1		*FRONT WHEEL SPOILER-LH (Supplementary)	Torn	73.00 FS	*58.40 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**    **24,674.00**    **3,059.12**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	700.00	0.00
3	TO RENEW AND REINSTALL AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,400.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHTS. TO REPAIR BONNET. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,850.00	500.00
5	TO RESPRAY FRONT BUMPER AND BONNET	New	2,000.00	1,100.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>8,622.00</b>	<b>2,272.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >