

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010774/KVY3N2**Date:** 22/11/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00106432101

Claimant Vehicle No : SLR3400Y **Insured Vehicle No :** GBH7733G

Date of Loss: 06/10/2021 Nature of Claim: TP Claim No: SNM21D205712/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLR3400Y**

Make & Model: HYUNDAI ELANTRA, 1.6 (A) Engine No: G4FGHU630455

Reg. Date: 11/08/2017 (Man. Year: 2017) Chassis No: KMHD841CMJU527274

Colour: White Odometer: 52191 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17

Front Left Side: Falken 8 mm Rear Left Side: Falken 8 mm

Front Right Side: Falken 8 mm Rear Right Side: Falken 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	856.00	641.00	215.00	25.12
Miscellaneous Items	275.00	215.00	60.00	21.82
Labour	197.40	79.80	117.60	59.57
Paintwork Labour	525.83	525.83	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,854.23	1,461.63	392.60	21.17
Approved Total (Overridden) (S\$)		1,100.00		
(S\$)	1,854.23	1,100.00	754.23	40.68
+ GST 7.00/7.00% (S\$)	129.80	77.00	52.80	40.68
Nett Amount (S\$)	1,984.03	1,177.00	807.03	40.68

INSPECTION

Date of Assignment: 19/10/2021 Present Location: S & H Motor Pte Ltd (Sin Ming)

Date Inspected: 20/10/2021 Inspected At: S & H Motor Pte Ltd (Sin Ming)
160 Sin Ming Drive #07-02, Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Nov 2021)
Parts:	143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR3400Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Parts		856.00 F	*641.00 F
F=Franchise part.						
				Total Parts (S\$)	856.00	641.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	misc	275.00	215.00
Sub Total (\$\$)			275.00	215.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Labour for paintwork	New	525.83	525.83
<u>Labour Items</u>				
2	Labour for panel/mechanical	New	197.40	79.80
Gross Labour Cost (\$\$)			723.23	605.63

Report was unsubmitted during this print-out.

< END OF ESTIMATES >