# LKK Auto Consultants #01-25 Paya Ubi Industrial Park, 51 Ubi Avenue 1 408933

KK LAU

**SLR3400Y** 

Insurer Reference:

Repairer Reference: 044015

Date calculated: 18/11/2021 12:41 PM

Full Report Registration: SLR3400Y

Printed: 18/11/2021 12:41 PM

### **Summary Information**

Claim

Location: Singapore (SG)

Work Provider:

China Taiping Insurance

(Singapore) Pte Ltd

Printed by:

Claim Reference:

Estimated Repair Time: Actual Repair Days:

Currency:
Date of Incident:
Hire Car Start:

Hire Car End:

SGD 06/10/21

### **Vehicle Details**

Vehicle

Manufacturer: HYUNDAI
Model: ELANTRA (AD)
Sub Model: BASE MODEL
Model Sheet Number: 30 92 01

Registration: VIN number:

Odometer: **Model Specs** 

TWO COAT METALLIC PREPARE OFF VEHICLE


### **Vehicle Condition**

#### **Vehicle Status**

Pre-Accident Damage: Date of Inspection:

#### **Damage Areas**

All Underbody



# Labour

	Time Base 10 W	U/h	Pric	e = 42.	00 SGD/h
Code	Description	•		WU	Price SGD
86520R00	RENEW REAR BUMPER INCLUDES: R + R OUTER TAIL LAMPS AND NECESSARY ATTACHED PARTS			9.0	37.80
87200R00	RENEW BADGE "HYUNDAI"			2.0	8.40
87400R00 ZAX	RENEW TYPE BADGE BOOTLID			3.0	12.60
2711	REAR PANEL REPAIR				
2931	BOOTLID REPAIR			5.0*	21.00
	Labour Cost		Hrs	wu	
	Panel / Mechanical Labour		1.90	19.0	79.80
	Total of Labour			1	79.80
Paint					
Paint Work	SYSTEM AZT	-	Tin	ne Basis	10 WU/h
Code	<b>Description - TWO COAT METALLIC</b>			WU	Price SGD
	REAR PANEL NEW PART PAINTING			23.0	
	BOOTLID NEW PART PAINTING			12.0	
	REAR BUMPER NEW PART PAINT K1G/P			18.0	
Paint Material	Per Part				
Code	Description				Price SGD
2711	REAR PANEL NEW PART PAINTING				28.60
2931	BOOTLID NEW PART PAINTING				29.93
2583	REAR BUMPER NEW PART PAINT K1G/P				64.80
	<b>Labour Cost - Paint</b> Factor	42.00 SGD/h	Hrs	WU	Price SGD
	Time Paint	42.00 SGD/II		53.0	
	Preparation Main Work Metal		2.50	25.0	105.00
	Preparation Comp. Work Plastic		0.80	8.0	33.60
	Total	10 WU/h	8.60	86.0	361.20
	Material Cost - Paint				Price SGD
	New Part Painting				58.53
	New Part Painting - Plastic K1G/PUR				64.80
	Material-constant Metal Preparation				28.60
	Material-constant Plastic				12.70
	Total				164.63
<b>Spare Parts</b>					

				prices as at 2015-06-01
Code	Description	Part Number	Part Source	Price SGD

Code	Description	Part Number	Part Source	Price SGD
3015	BADGE "HYUNDAI"	86321F2000	Original	25.00
3014	BADGE MODEL	86315F2000	Original	20.00
3023	BADGE SPORT	86316F2000	Original	16.00
2583	REAR BUMPER	86611F2000	Original	350.00
2593	REAR BUMPER SPOILER	86612F2000	Original	130.00
f: OEM Parts n: Non-OEM Parts u: Used parts	Savings Subtotal Fixed Sundry Parts	Price		0.00 541.00 100.00
	Total			641.00

### **Extras**

Code	Description	Price SGD
1000	Electrical work Electrical work	15.00*
1001	REAR PARKING SENSORS REAR BUMPER	200.00*
	Total Extras	215.00

# **Final Calculation**

	CCD	
	SGD	SGD
Parts	541.00	
Fixed Sundry Parts Price	100.00	
Total Parts		641.00
Labour Time Base 10 WU/h		
Total 19.0 WU X 42.00 SGD/h	79.80	
Total of Labour		79.80
Total Of Extras		215.00
Paint Work Time Base 10 WU/h		
Labour Cost 86.0 WU X 42.00 SGD/h	361.20	
Material Cost	164.63	
Total Paint Including Material		525.83
Repair Cost Excludes GST		1,461.63
GST (+7.0%)		102.31
Repair Cost Included GST		1,563.94

#### Comments

\* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

#### **Assessment Note**

No assessment notes entered.