

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG21010778/GQF3N2**Date:** 12/01/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : GBB61P**Insured Vehicle No :** SFC261B

Date of Loss: 15/10/2021

Nature of Claim: TP

Claim No: 2046280659SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBB61P**

Make & Model: ISUZU TFR87JDR, 1.9 D D/CAB (A)

Engine No: TS8948

Reg. Date: 30/05/2019 (Man. Year: 2019)

Chassis No: MPATFR87JKT001320

Colour: Grey

Odometer: 15683 km

Engine Capacity: 1898 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/70R15

Rear Tyre Size: 215/70R15

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 20/10/2021

Date Inspected: 20/12/2021 Inspected At:

Garage 13 Pte Ltd (HQ)

8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #03-46

Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE: \$77,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	0.00 F	*- F
2	1		*FRT BUMPER SIDE RETAINER	Cut	0.00 F	*- F
3	1		*FRT RH BUMPER FOG LAMP	Broken	0.00 F	*- F
4	1		*FRT RH HEADLAMP ASSY	Broken	0.00 F	*- F
5	1		*FRT RH FENDER	Repair	0.00 F	*- F
6	1		*REAR BUMPER	Repair	0.00 F	*- F
7	1		*REAR BUMPER STEP GARNISH	Deformed	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >