



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 6064B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	BUCKLED	565.00	541.00
12	FRONT BUMPER CLIPS @\$3.80	NECESSARY	45.60	45.60
1	FRONT BUMPER BRACKET RH	TO REPAIR SEE LABOUR	82.60	-
1	FRONT BUMPER SPONGE	SERVICEABLE	115.90	-
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	435.00	-
1	FRONT BUMPER FOG LAMP RH	SERVICEABLE	110.00	-
1	FRONT BUMPER FOG LAMP COVER RH	CRACKED	203.00	105.80
1	FRONT BUMPER CENTER AIR GRILLE	DENTED	169.95	169.95
1	FRONT BUMPER CORNER RETAINER RH	DISTORTED	286.40	125.00
1	GRILLE	DENTED	715.90	374.00
1	GRILLE EMBLEM	NECESSARY	95.00	95.00
1	HEADLAMP RH	CUT	2,488.95	2,223.00
	LESS 25% DISCOUNT		-1,328.33	-919.84
			3,984.97	2,759.51
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT NUMBER PLATE (SN)	DENTED	45.00	45.00
			45.00	45.00
	<b><u>LABOUR</u></b>			
	TO CONDUCT ELECTRICAL CHECK ,FOCUS HEADLAMP.		30.00	20.00
	LABOUR CHARGE-PANEL BEATING ,REPAIRING OF FRONT HEADLAMP PANEL ,SUPPORT & PART REPLACEMENT.		400.00	220.00
	TO SPRAY PAINTING AFFECTED AREAS .		380.00	220.00
			810.00	460.00
	<b>GRAND TOTAL</b>		<b>4,839.97</b>	<b>3,264.51</b>



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,600.00</b>
---	--	--	-----------------

Report Ref No. CS/SMO21010781/Knf3q2

**KONG SENG CHEONG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**