

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010782/AQY3N2**Date:** 28/01/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00005842101	
Claimant Vehicle No :	SLZ9167P	Insured Vehicle No :	SMC9138H	
Date of Loss:	17/10/2021	Nature of Claim:	TP	Claim No: SNM21D205932/C02/CHEESC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ9167P		
Make & Model:	SUBARU IMPREZA 4D, 2.0 I-S EYESIGHT AWD CVT (A)	Engine No:	FB20YD79172
Reg. Date:	23/05/2018 (Man. Year: 2018)	Chassis No:	JF1GK7KL5JG009219
Colour:	Silver	Odometer:	49902 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,388.80	2,066.80	2,322.00	52.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,360.00	1,350.00	1,010.00	42.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,748.80	3,416.80	3,332.00	49.37
Approved Total (Overridden) (S\$)		2,700.00		
Nett Amount (S\$)	6,748.80	2,700.00	4,048.80	59.99

INSPECTION

Date of Assignment:	06/12/2021	
Date Inspected:	20/10/2021	Inspected At: SIN YU SIN WORKSHOP 1 KAKI BUKIT AVE 6 #01-82 AUTOBAY SINGAPORE 417883
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Jan 2022)

Parts: 143 SUBARU IMPREZA 4D 2.0 I-S EYESIGHT AWD CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLZ9167P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Repair	1,092.00 FL	*- FL
2	1		*REAR BOOT LID LOGO EMBLEM	Necessary	85.00 FL	*85.00 FL
3	1		*REAR BOOT LID SUBARU EMBLEM	Necessary	80.00 FL	*80.00 FL
4	1		*REAR BOOT LID SYMMETRICAL EMBLEM	Necessary	55.00 FL	*55.00 FL
5	1		*REAR BOOT LID AWD EMBLEM	Necessary	62.00 FL	*62.00 FL
6	1		*REAR BOOT LID IMPREZA EMBLEM	Necessary	78.00 FL	*78.00 FL
7	1		*REAR BOOT LID EYESIGHT EMBLEM	Necessary	53.00 FL	*53.00 FL
8	1		*REAR BOOT LID WEATHER STRIP	Not Necessary	246.00 FL	*- FL
9	1		*REAR BOOT LID MECHANISM LOCK	Not Necessary	230.00 FL	*- FL
10	1		*REAR BOOT LID LOCK STRIKER	Not Necessary	55.00 FL	*- FL
11	1		*REAR BOOT LID KEYLESS SMART	Not Necessary	167.00 FL	*- FL
12	1		*REAR BUMPER	Deformed	780.00 FL	*456.00 FL
13	1		*REAR BUMPER REVERSE SENSOR (4 Pcs)	Damaged (2 Pcs only)	872.00 FL	*436.00 FL
14	4		*REAR BUMPER REVERSE SENSOR HOLDER	Necessary	224.00 FL	*80.00 FL
15	1		*REAR BUMPER REINFORCEMENT BEAM	Dented	288.00 FL	*288.00 FL
16	2		*REAR BUMPER SIDE RETAINER L/R	Not Necessary	196.00 FL	*- FL
17	1		*REAR BUMPER TOWING COVER	Deformed	43.00 FL	*43.00 FL
18	1		*REAR END PANEL	Dented	520.00 FL	*520.00 FL
19	1		*REAR END PANEL GARNISH	Cracked	285.00 FL	*285.00 FL
20	1		*REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
21	1		*REAR END PANEL GARNISH CLIP	Necessary	30.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,471.00	2,571.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,082.20	504.20
Total Parts (\$\$)	4,388.80	2,066.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRINGS	New	80.00	30.00
2	TO REMOVE,REFIX REAR REVERSE SENSOR	New	100.00	60.00
3	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS,GARNISH,SEAT,ETC FOR NECESSARY REPAIR	New	180.00	60.00
4	TO STRAIGHTEN,REPAIR,REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,000.00	600.00
5	TO SPRAY PAINTING ON AFFECTED AREA	New	1,000.00	600.00
Gross Labour Cost (\$)			2,360.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >