

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21010790/R1GS3Q2**Date:** 12/01/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210005836
<b>Claimant Vehicle No :</b>	SHD1054Y	<b>Insured Vehicle No :</b>	SMX6848B
Date of Loss:	20/10/2021	Nature of Claim:	TP
		Claim No:	8347377356SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHD1054Y</b>	Engine No:	D4DFDH314450
Make & Model:	KIA OPTIMA, 1.7 D (A)	Chassis No:	KNAGM414MF5658870
Reg. Date:	21/01/2016 (Man. Year: 2015)	Odometer:	566305 km
Colour:	Grey		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/65 R16	Rear Tyre Size:	205/65 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,500.00	1,041.80	1,458.20	58.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,590.00	440.00	1,150.00	72.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,090.00</b>	<b>1,481.80</b>	<b>2,608.20</b>	<b>63.77</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,150.00</b>		
<b>(S\$)</b>	4,090.00	1,150.00	2,940.00	71.88
<b>+ GST 7.00/7.00% (S\$)</b>	286.30	80.50	205.80	71.88
<b>Nett Amount (S\$)</b>	<b>4,376.30</b>	<b>1,230.50</b>	<b>3,145.80</b>	<b>71.88</b>
<b>+ Loss of Use (2.5 x S\$40.00/day) (S\$)</b>		100.00		
<b>+ Car Rental (2.5 x S\$67.41/day) (S\$)</b>		168.53		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>1,501.03</b>		
<b>Global Sum Settlement (S\$)</b>		<b>1,500.00</b>		

**INSPECTION**

Date of Assignment:	20/10/2021		
Date Inspected:	25/10/2021	Inspected At:	Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02 Singapore 486443
Estimated Period of Repair:	5.0 days		

**Adjuster:** MOHD RASUL**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID CRDI	Not Necessary	29.00 FL	*- FL
2	1		*BOOT LID LOWER GARNISH	Not Necessary	290.00 FL	*- FL
3	1		*REAR BUMPER	Deformed	696.00 FL	*696.00 FL
4	1		*REAR BUMPER LOWER COVER	Scratched	206.00 FL	*206.00 FL
5	2		*REAR BUMPER SIDE BRACKET O/S & N/S	Not Necessary	58.00 FL	*- FL
6	1		*REAR BUMPER INNER SPONGE	Not Necessary	114.00 FL	*- FL
7	1		*REAR BUMPER REINFORCEMENT	Not Necessary	607.00 FL	*- FL
8	2		*REAR BUMPER STAY O/S & N/S	Not Necessary	108.00 FL	*- FL
9	2		*REAR BUMPER REINFORCEMENT LOWER BRACKET	Not Necessary	36.00 FL	*- FL
10	2		*REAR BUMPER REINFORCEMENT UPPER BRACKET	Not Necessary	36.00 FL	*- FL
11	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*30.00 FS
12	1		*SET BOOTLID LOWER GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
13	1		*SET BOOTLID STICKERS	Not Necessary	100.00 FS	*- FS
14	1		*SET REVERSE SENSOR	Scratched	280.00 FS	*200.00 FS
15	1		*SUNDRY	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>2,718.00</b>	<b>1,132.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	218.00	90.20
<b>Total Parts (\$)</b>	<b>2,500.00</b>	<b>1,041.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANLTE /REPLACE REVERSE SENSOT TO NEW BUMPER AND RESET TO THE SAME	New	60.00	40.00
2	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS	New	180.00	0.00
3	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF THE SAME ,ETC	New	650.00	200.00
4	TO PUTTY AND SPRAY PAINTING ON BOOTLID LOWER GARNISH ,REAR BUMPER ,END PANEL	New	600.00	200.00
5	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	100.00	0.00
			<b>Gross Labour Cost (\$)</b>	<b>1,590.00</b>
				<b>440.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >