

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBG 1097D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR MUDGUARD (CONSISTENT)	NOT NECESSARY	135.00	-
1	REAR RH SIGNAL (CONSISTENT)	NOT NECESSARY	65.00	-
1	TAIL LAMP (CONSISTENT)	NOT NECESSARY	130.00	-
1	REAR CENTRE PANEL (CONSISTENT)	NOT NECESSARY	150.00	-
1	HANDLE BAR (CONSISTENT)	NOT NECESSARY	95.00	-
1	BRAKE LEVER (CONSISTENT)	CUT	65.00	65.00
1	EXHAUST GUARD (CONSISTENT)	NOT NECESSARY	180.00	-
1	REAR LH TAIL SIDE PANEL (CONSISTENT)	CUT	120.00	120.00
1	GEAR PEDAL (CONSISTENT)	BENT	80.00	80.00
1	GEAR ROD (CONSISTENT)	NOT NECESSARY	75.00	-
1	SET MIRROR -UNIVERSAL (CONSISTENT)	BROKEN	180.00	180.00
1	LH TANK COVER (CONSISTENT)	CUT	250.00	250.00
1	ENGINE COVER (CONSISTENT)	NOT NECESSARY	195.00	-
	LESS 10% DISCOUNT		-172.00	-69.50
			1,548.00	625.50
	<u>LABOUR</u>			
	TOWING FEE.	NOT NECESSARY	40.00	-
	REMOVE & REPLACE ABOVE PARTS ,ALIGN & ETC.		250.00	150.00
	PUTTY & TOUCH UP PAINT WORK.		200.00	150.00
	FORK REPRESS.		180.00	120.00
			670.00	420.00
	GRAND TOTAL		2,218.00	1,045.50

RECOMMENDED COST OF LUMP SUM REPAIRS		800.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM21010792/Trs3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

HO LEONG CHUAN

Automotive Assessor

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.