11/16/21, 11:42 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21010793/ETY3N2

16/11/2021 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMCVSNW00012392104

Claimant Vehicle

SLR8144D

Insured

GBC8716B

No:

Vehicle No:

Date of Loss:

17/10/2021

Nature of Claim: TP

Claim

SNM21D205936/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SLR8144D Reg No:

Make & Model: MAZDA 3, 1.5 SEDAN AT EU6 (A)

29/08/2017 (Man. Year: 2017)

Engine No: Chassis No:

Odometer:

P520454874 JM6BN22A8H0162674

49876 km

Reg. Date: Colour:

1496 cc

Engine Capacity:

N/A

Market Value/New Car Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Engine Modification: Yes

Pre-accident Condition: Nο

CONDITION OF TYRES

Front Tyre Size: Front Left Side:

205/60R16 Toyo 5 mm Rear Tyre Size: Rear Left Side: Rear Right Side: 205/60R16

Tovo 5 mm Toyo 5 mm

Front Right Side: Toyo 5 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,234.00	1,656.88	577.12	25.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	470.00	530.00	53.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$	3,234.00	2,126.88	1,107.12	34.23
Approved Total (Overridden) (S\$)	1,700.00		
(S\$	3,234.00	1,700.00	1,534.00	47.43
+ GST 7.00/7.00% (S\$) 226.38	119.00	107.38	47.43
Nett Amount (S\$	3,460.38	1,819.00	1,641.38	47.43

INSPECTION

Adjuster:

Date of Assignment: 20/10/2021

CHEN TSUE YEE

Date Inspected:

21/10/2021 Inspected At:

Lion City Rental (jalan Lam Huat) (HQ) 60 Jalan Lam Huat, 04-35/36 Carros Centre

Singapore 737869

Estimated Period of Repair:

3.0 days

Manager:

DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Nov 2021)

Parts: 143 MAZDA 3 1.5 SEDAN AT EU6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLR8144D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Dented	1,500.00 FL	*1,062.00 FL
2	1		*FRONT SIDE MIRROR ASSEMBLY (LH)	Broken	980.00 FL	*821.60 FL
3 F=Fra	1 inchise	part. S=SpcNe	*SET FRONT DOOR GET-GO STICKER ett. L=ListItemDisc.	Necessary	250.00 FS	*150.00 FS
				Sub Total (S\$)	2,730.00	2,033.60
	- List Item Discount on L Items 20.00/20.00% (S\$)				496.00	376.72
				Total Parts (S\$)	2,234.00	1,656.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO RESPRAY FRONT DOOR (LH) AND SIDE MIRROR COVER (LH)	New	500.00	270.00
2	TO LABOUR CHARGE FOR REMOVING FRONT DOOR (LH) OUT TO FACILITATE REPAIRS OF DAMAGE PARTS	New	500.00	200.00
	Gross Labou	Gross Labour Cost (S\$)		470.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >