

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
	CHINA TAIPING INSURANCE (S) PTE LTD		Ref:	CS3/CTI21008519/Gvcn2-1
	3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date:	12/11/2021
			Code:	СТІ
1.	Poli	cy Particulars :- THIRD PAR	Y CLAIM (RESURVEY INSPECTION)	
	Insured Veh.	PC 604C	Veh. Inspected	PC 7998U
	Policy No.	DMB1SNW00012062004	Coverage (\$)	0.00
	Claim No.	SNM21D204440/C02/LEWLC	Excess (\$)	0.00
	Assign From	JENNY LEW	Assign Date	20/10/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE COMMUTER	c.c	2754
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	GDH2232001298	Colour	WHITE
	Odometer	211620 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	MICHELIN	6 mm
	L/H Front Tyre	195 R15	MICHELIN	6 mm
	R/H Rear Tyre	195 R15	MICHELIN	6 mm
	L/H Rear Tyre	195 R15	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.			
	REPAIR CONDITION SEE DETAILS.			
5.	General Information			
	Accident Date	10/08/2021	Inspection Date	25/10/2021
	Survey held at	CARSMITH PTE LTD		
		BARTLEY BIZ CENTRE, 13 KAKI BUKIT ROAD 4 #01-20 SINGAPORE 417807		
5a.	Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 14 Working Days			