

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21010795/T1GS3Q2**Date:** 07/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993661
Claimant Vehicle No :	SMT6344J	Insured Vehicle No :	SLW268G
Date of Loss:	17/10/2021	Nature of Claim:	TP
		Claim No:	2086069487SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT6344J	Engine No:	28291480158354
Make & Model:	MERCEDES-BENZ CLA180, 1.6 (A)	Chassis No:	WDD1183842N007445
Reg. Date:	09/07/2020 (Man. Year: 2019)	Odometer:	43432 km
Colour:	Silver		
Engine Capacity:	1332 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Hankook 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,924.60	3,358.90	2,565.70	43.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,970.00	890.00	1,080.00	54.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,894.60	4,248.90	3,645.70	46.18
Approved Total (Overridden) (S\$)		3,400.00		
(S\$)	7,894.60	3,400.00	4,494.60	56.93
+ GST 7.00/7.00% (S\$)	552.62	238.00	314.62	56.93
Nett Amount (S\$)	8,447.22	3,638.00	4,809.22	56.93
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,795.45		
Global Sum Settlement (S\$)		3,750.00		

INSPECTION

Date of Assignment:	20/10/2021	Carz Auto Services Pte Ltd (HQ)
Date Inspected:	22/10/2021 Inspected At:	1 KAKI BUKIT AVE 6 #02-35 AUTOBAY @ KAKI BUKIT
Estimated Period of Repair:	3.0 days	Singapore 417883

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,900.00 FL	*1,560.43 FL
2	2		*REAR BUMPER SIDE RETAINER	Not Necessary	220.00 FL	*- FL
3	2		*REAR BUMPER LOWER BRACKET	Not Necessary	180.00 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Bent	570.00 FL	*464.36 FL
5	1		*REAR BUMPER LOWER COVER	Deformed	670.00 FL	*541.77 FL
6	1		*REAR BUMPER REFLECTOR LH	Deformed	45.00 FL	*45.00 FL
7	1		*REAR BUMPER CENTRE MOULDING (CHROME)	Cut	190.00 FL	*190.00 FL
8	1		*REAR BUMPER LEFT MOULDING (CHROME)	Cut	180.00 FL	*180.00 FL
9	1		*REAR TAIL PIPE TRIM (LH) CHROME	Cut	145.00 FL	*145.00 FL
10	1		*TOWING COVER	Not Necessary	50.00 FL	*- FL
11	1		*REAR EMBLEM (CLA180)	Necessary	243.00 FL	*180.00 FL
12	1		*REAR TAIL LAMP LH	Not Necessary	836.00 FL	*- FL
13	1		*REAR MOUNT BRACKET (CENTRE)	Cracked	120.00 FL	*120.00 FL
14	1		*REAR SIDE MOUNT LH	Not Necessary	120.00 FL	*- FL
15	1		*REAR SIDE GRILLE LH	Not Necessary	25.00 FL	*- FL
16	10		*REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
17	1		*REAR NUMBER PLATE	Bent	50.00 FS	*45.00 FS
18	1		*REVERSE SENSOR	Not Working (1 PCS ONLY)	880.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,474.00	3,701.56
- List Item Discount on L Items 10.00/10.00% (S\$)	549.40	342.66
Total Parts (S\$)	5,924.60	3,358.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND RENEW REAR DAMAGED PARTS REPLACE REALIGNED ALL AFFECTED PARTS	New	800.00	300.00
2	TO RESPRAY AFFECTED AREAS	New	800.00	500.00
3	TO REMOVE/REFIX WIRING CHECKS	New	120.00	30.00
4	TO TUFFCOAT AFFECTED AREA	New	150.00	30.00
5	TO REMOVE/REPLACE REVERSE SENSORS	New	100.00	30.00
			Gross Labour Cost (\$)	890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >