

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21010799/URA3Q2**Date:** 14/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993682
Claimant Vehicle No :	SMP3218G	Insured Vehicle No :	YP7720D
Date of Loss:	17/10/2021	Nature of Claim:	TP
		Claim No:	2632181462SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP3218G	Engine No:	PE21271276
Make & Model:	MAZDA 6, 2.0 SEDAN EXECUTIVE 2WD (A)	Chassis No:	JM6GL1072K0315531
Reg. Date:	20/09/2019 (Man. Year: 2019)	Odometer:	36585 km
Colour:	Blue		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,607.40	5,955.44	4,651.96	43.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,970.00	1,170.00	2,800.00	70.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,577.40	7,125.44	7,451.96	51.12
Approved Total (Overridden) (S\$)		5,700.00		
Nett Amount (S\$)	14,577.40	5,700.00	8,877.40	60.90
+ Car Rental (5.0 x S\$120.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,307.45		

INSPECTION

Date of Assignment:	20/10/2021		
Date Inspected:	21/10/2021	Inspected At:	Zoom Autowerks Pte Ltd (HQ) 15 Kaki Bukit Road 4, #01-53 Singapore 417808
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** Jaslin Kok Chin Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,218.00 FL	*- FL
2	1		*FRONT BUMPER CENTRE AIR-GRILLE	Not Necessary	215.00 FL	*- FL
3	1		*FRONT BUMPER SIDE RETAINER	Not Necessary	150.00 FL	*- FL
4	1		*FRONT BUMPER SPONGE	Not Necessary	267.00 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Repair	528.00 FL	*- FL
6	1		*FRONT BUMPER FOG LAMP	Not Necessary	650.00 FL	*- FL
7	1		*FRONT BUMPER FOG LAMP GARNISH	Not Necessary	216.00 FL	*- FL
8	1		*FRONT BUMPER TOP	Deformed	276.00 FL	*225.30 FL
9	1		*FRONT BUMPER SENSOR	Not Necessary	700.00 FL	*- FL
10	1		*FRONT BUMPER SENSOR BRACKET	Not Necessary	70.00 FL	*- FL
11	1		*FRONT BUMPER NUMBER PLATE GARNISH	Not Necessary	125.00 FL	*- FL
12	1		*FRONT BUMPER RIVETS	Necessary	48.00 FL	*48.00 FL
13	1		*FRONT BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
14	1		*RADIATOR GRILLE	Cracked	368.00 FL	*368.00 FL
15	2		*RADIATOR SIDE GRILLE CHROME	Cracked	396.00 FL	*396.00 FL
16	1		*RADIATOR INNER	Cracked	350.00 FL	*350.00 FL
17	1		*RADIATOR GRILLE LOGO	Scratched	108.00 FL	*85.00 FL
18	1		*FRONT SUPPORT PANEL TOP GARNISH	Serviceable	298.00 FL	*- FL
19	1		*FRONT SUPPORT TOP GARNISH CLIPS	Necessary	45.00 FL	*45.00 FL
20	1		*FRONT SUPPORT PANEL	Repair	1,098.00 FL	*- FL
21	2		*FRONT HEADLAMP ASSY	Cracked	5,872.00 FL	*5,872.00 FL
22	1		*FRONT NUMBER PLATE W/GARNISH	Not Necessary	55.00 FS	*- FS
23	1		*RADIATOR COOLANT	Not Necessary	110.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	13,218.00	7,444.30
- List Item Discount on L Items 20.00/20.00% (\$)	2,610.60	1,488.86
Total Parts (\$)	10,607.40	5,955.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPAIR & RENEW FRONT AFFECTED ACCIDENT AREAS	New	1,400.00	600.00
2	TO PUTTY ,SPRAY PAINT ON AFFECTED FRONT ACCIDENT AREAS	New	1,600.00	550.00
3	TO CONDUCT RADIATOR PRESSURE TEST	New	120.00	0.00
4	TO DISCHARGE & CHARGE UP AC- GAS	New	150.00	0.00
5	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
6	TO RE-SET ,RE-PROGRAMME & CALIBRE ENGINE DIAGNOSTIC MANAGEMENT	New	450.00	0.00
7	TO RUST PROOF AFFECTED AREAS	New	200.00	0.00
			Gross Labour Cost (S\$)	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >