

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21010800/APA3Q2**Date:** 20/12/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100506410
Claimant Vehicle No :	EY9288L	Insured Vehicle No :	SE5383K
Date of Loss:	19/10/2021	Nature of Claim:	TP
		Claim No:	1679034956SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	EY9288L	Engine No:	CJX034714
Make & Model:	AUDI S3, 2.0 TFSI Quattro (M)	Chassis No:	WAUZZZ8V0F1057705
Reg. Date:	29/11/2014 (Man. Year: 2014)	Odometer:	68157 km
Colour:	Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40 R18	Rear Tyre Size:	235/40 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,740.00	0.00	3,740.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,222.00	1,380.00	2,842.00	67.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,962.00	1,380.00	6,582.00	82.67
+ GST 7.00/7.00% (S\$)	557.34	96.60	460.74	82.67
Nett Amount (S\$)	8,519.34	1,476.60	7,042.74	82.67
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	20/10/2021		
Date Inspected:	20/10/2021	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR -LH	Repair	3,039.00 FS	*- FS
2	1		*REAR DOOR OUTER SEAL -LH	Not Necessary	161.00 FS	*- FS
3	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
4	1		*CLEANIG SOLUTION	Not Necessary	68.00 FS	*- FS
5	1		*APPLICATOR	Not Necessary	129.00 FS	*- FS
6	1		*DOOR CATCH	Not Necessary	94.00 FS	*- FS
7	1		*REAR ALUMINIUM RIM (NPA)	Repair	0.00 FS	*- FS
8	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS
Total Parts (\$\$)					3,740.00	0.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES INSPECT FOR DAMAGES	New	350.00	0.00
2	TO DISMANTLE AND RENEW LHS REAR DOOR .TO REPAIR LHS REAR FENDER RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,400.00	0.00
3	TO RESPRAY LHS REAR DOOR AND LHS REAR FENDER	New	2,000.00	1,100.00
4	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
5	TO CARRY OUT DIAGNOSTIC CHECK (*Check)	New	192.00	0.00
Gross Labour Cost (\$\$)			4,222.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >