

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III21010801/EPA3Q2**Date:** 30/03/2022**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MCV0002164\_01  
**Claimant Vehicle No :** SMX6597A **Insured Vehicle No :** PC3719K  
 Date of Loss: 18/10/2021 Nature of Claim: TP Claim No: MCV2021D0004524

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMX6597A**  
 Make & Model: MITSUBISHI OUTLANDER, 2.0 (A) Engine No: 4J11CY7036  
 Reg. Date: 25/01/2021 (Man. Year: 2020) Chassis No: GF7W0700983  
 Colour: White Odometer: 6070 km  
 Engine Capacity: 1998 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18  
 Front Left Side: Toyo 5 mm Rear Left Side: Toyo 5 mm  
 Front Right Side: Toyo 5 mm Rear Right Side: Toyo 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,791.00	6,329.00	462.00	6.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,187.00	3,277.00	1,910.00	36.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>11,978.00</b>	<b>9,606.00</b>	<b>2,372.00</b>	<b>19.80</b>
<b>+ GST 7.00/7.00% (S\$)</b>	838.46	672.42	166.04	19.80
<b>Nett Amount (S\$)</b>	<b>12,816.46</b>	<b>10,278.42</b>	<b>2,538.04</b>	<b>19.80</b>
<b>+ Car Rental (7.0 x S\$160.00/day + 7.00% GST) (S\$)</b>		1,198.40		
<b>Nett Liability (S\$)</b>		<b>11,476.82</b>		

**INSPECTION**

Date of Assignment: 20/10/2021  
 Date Inspected: 28/10/2021 Inspected At: Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)  
 209 Pandan Gardens  
 Singapore 609339  
 Estimated Period of Repair: 5.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 08 Feb 2022)

**Parts:** M1-SUV      MITSUBISHI OUTLANDER 2.0 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SMX6597A)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*HEADLAMP ASSY ,LH	Broken	1,948.00 FS	*1,948.00 FS
3	1		*LAMP ASSY ,FOG,FR LH	Not Necessary	350.00 FS	*- FS
4	1		*FACE ,FR BUMPER	Broken	863.00 FS	*863.00 FS
5	1		*BRACKET ,FR BUMPER SIDE ,LH	Broken	18.00 FS	*18.00 FS
6	1		*GARNISH ,FR BUMPER ,LH	Broken	48.00 FS	*48.00 FS
7	1		*GARNISH ,FR BUMPER SIDE	Broken	112.00 FS	*112.00 FS
8	1		*GARNISH ,FR BUMPER SIDE	Missing	220.00 FS	*220.00 FS
9	1		*GARNISH ,FR BUMPER SIDE	Broken	48.00 FS	*48.00 FS
10	1		*REINF ,FR BUMPER SIDE ,LH	Not Necessary	60.00 FS	*- FS
11	1		*REINFORCEMENT ,FR BMPR SIDE	Not Necessary	22.00 FS	*- FS
12	1		*FENDER ,FR LH	Dented	622.00 FS	*622.00 FS
13	1		*SHIELD ,FR WHEELHOUSE LH	Crushed	164.00 FS	*164.00 FS
14	1		*MOULDING ,FR BUMPER ,LH	Missing	97.00 FS	*97.00 FS
15	1		*MOULDING ,FR WHEEL ARCH ,LH	Cut	168.00 FS	*168.00 FS
16	1		*WHEEL ,DISC	Cut	974.00 FS	*974.00 FS
17	1		*EXTENSION ,FR BUMPER	Cut	517.00 FS	*517.00 FS
18	10		*RIVET	Necessary	50.00 FS	*50.00 FS
19	10		*CLIPS	Necessary	30.00 FS	*30.00 FS
20	10		*CLIPS	Necessary	20.00 FS	*20.00 FS
21	1		*STRUT ,FR SUSP ,LH	Bent	410.00 FS	*410.00 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**      **6,791.00**      **6,329.00**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPLACE LH FRONT UNDERCARRIAGE PARTS	New	225.00	225.00
2	REPLACE FR BUMPER ,FRT LH FENDER & AFFECTED AREA	New	1,920.00	1,280.00
3	PAINT WORK ON FRT BUMPER & FRT LH FENDER	New	1,650.00	1,100.00
4	PERFORM RUST PREVENTION	New	100.00	30.00
5	TO APPLY SEALANT ON AFFECTED AREA	New	50.00	0.00
6	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	120.00	120.00
7	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	280.00	280.00
8	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	192.00	192.00
9	TO TRANSFER FRT LH RIM INCLUDING BALANCING	New	50.00	50.00
10	TO SUPPLY FRT LH TYRE	New	600.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,187.00</b>	<b>3,277.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >