

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS21010805/EVF3N2**Date:** 26/11/2021REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	MPC21P00192100
Claimant Vehicle No :	SKX9490C	Insured Vehicle No :	SJP4036T
Date of Loss:	19/10/2021	Nature of Claim:	TP
		Claim No:	DMPC2100374H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX9490C	Engine No:	3ZZ4822133
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106126771
Reg. Date:	15/01/2009 (Man. Year: 2008)	Odometer:	427279 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,642.07	4,381.15	2,260.92	34.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,730.00	2,420.00	1,310.00	35.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,372.07	6,801.15	3,570.92	34.43
Approved Total (Overridden) (S\$)		5,400.00		
(S\$)	10,372.07	5,400.00	4,972.07	47.94
+ GST 7.00/7.00% (S\$)	726.04	378.00	348.04	47.94
Nett Amount (S\$)	11,098.11	5,778.00	5,320.11	47.94

INSPECTION

Date of Assignment:	21/10/2021	
Date Inspected:	26/10/2021 Inspected At:	Efficient Motor & Engineering Works Pte Ltd (HQ) 56 Loyang Way #06-07, Loyang Enterprise Building Singapore 508775
Estimated Period of Repair:	10.0 days	

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 26 Nov 2021)**Parts:** 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SKX9490C)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	612.00 FL	*612.00 FL
2	2		*REAR BUMPER REFLECTOR LH/RH	Not Necessary	101.20 FL	*- FL
3	2		*REAR BUMPER SIDE RETAINER LH/RH	Broken	123.40 FL	*123.40 FL
4	2		*REAR BUMPER SIDE RETAINER NO 2 LH/RH	Broken	77.20 FL	*77.20 FL
5	2		*REAR BUMPER UPPER RETAINER LH/RH	Broken	120.60 FL	*120.60 FL
6	1		*REAR BUMPER SPONGE	Broken	142.60 FL	*142.60 FL
7	2		*REAR REINFORCEMENT BRACKET LH/RH	Dented	184.00 FL	*184.00 FL
8	1		*BOOTLID	Dented	873.60 FL	*773.60 FL
9	2		*BOOTLID HINGE LH/RH	Not Necessary	157.20 FL	*- FL
10	1		*BOOTLID LOCK ASSY	Bent	111.80 FL	*111.80 FL
11	2		*BOOTLID REFLECTOR LH/RH	Cracked	451.60 FL	*451.60 FL
12	1		*BOOTLID CHROME MOULDING	Not Necessary	269.30 FL	*- FL
13	1		*BOOTLID EMBLEM 1.6	Necessary	45.80 FL	*45.80 FL
14	1		*BOOTLID EMBLEM ALTIS	Necessary	49.10 FL	*49.10 FL
15	1		*BOOTLID EMBLEM COROLLA	Necessary	48.20 FL	*48.20 FL
16	1		*BOOTLID EMBLEM LOGO	Necessary	60.50 FL	*60.50 FL
17	1		*BOOTLID WEATHERSTRIP	Torn	194.20 FL	*194.20 FL
18	2		*TAILLAMP LH/RH	Cut	500.20 FL	*500.20 FL
19	1		*TAILLAMP PANEL LH	Repair	87.30 FL	*- FL
20	1		*TAILLAMP PANEL RH	Repair	87.30 FL	*- FL
21	1		*REAR END PANEL	Dented	670.00 FL	*670.00 FL
22	1		*REAR END PANEL GARNISH	Crushed	213.80 FL	*213.80 FL
23	1		*SPARE WHEEL PANEL	Dented	818.10 FL	*818.10 FL
24	1		*SPARE WHEEL TOP BOARD	Torn	291.50 FL	*291.50 FL
25	1		*REAR FENDER LH	Repair	1,082.80 FL	*- FL
26	1		*REAR FENDER RH	Repair	1,082.80 FL	*- FL
27	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
28	1		*REVERSE SENSOR	Broken	200.00 FS	*200.00 FS
29	1		*REAR NO PLATE	Cut	50.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,756.10	5,753.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,114.03	1,372.05
Total Parts (\$\$)	6,642.07	4,381.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT/WELD,PANEL BEAT & ALIGN REAR PORTION,TO REMOVE & REPLACE DAMAGED PARTS	New	1,500.00	1,200.00
2	TO APPLY ANTI RUST COAT AND TUFF KOTE REPAIRED AREAS	New	100.00	30.00
3	TO CHECK AND RECTIFY LIGHTING & WIRING	New	80.00	30.00
4	TO REMOVE & REPLACE REVERSE SENSOR	New	100.00	30.00
5	TO REMOVE & REFIT SPARE TYRE,INTERIOR TRIMS TO FACILITATE THE REPAIR	New	100.00	50.00
6	TO PUTTY,SPRAY PAINTING REAR BUMPER,REAR END PANEL,BOOTLID,SPARE WHEEL PANEL,REAR FENDER LH/RH & OTHER AFFECTED AREAS	New	1,600.00	1,000.00
7	TO TRANSFER BOOTLID COMPONENTS TO NEW BOOTLID	New	150.00	50.00
8	TO REMOVE & REFIT EXHAUST SYSTEM TO ASSIST WORKLOAD	New	100.00	30.00
Gross Labour Cost (\$)			3,730.00	2,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >