

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010807/EVY3N2**Date:** 09/11/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00051732101
Claimant Vehicle No :	SMF3138G	Insured Vehicle No :	SMT3341L
Date of Loss:	14/10/2021	Nature of Claim:	TP
		Claim No:	SNM21D205973/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF3138G	Engine No:	3A92UGY0640
Make & Model:	MITSUBISHI ATTRAGE, 1.2 (A)	Chassis No:	MMBSTA13AJH002213
Reg. Date:	24/10/2018 (Man. Year: 2018)	Odometer:	82565 km
Colour:	White		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55R15	Rear Tyre Size:	185/55R15
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,744.06	898.40	1,845.66	67.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,130.00	990.00	1,140.00	53.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,874.06	1,888.40	2,985.66	61.26
Approved Total (Overridden) (S\$)		1,500.00		
(S\$)	4,874.06	1,500.00	3,374.06	69.22
+ GST 7.00/7.00% (S\$)	341.18	105.00	236.18	69.22
Nett Amount (S\$)	5,215.24	1,605.00	3,610.24	69.22

INSPECTION

Date of Assignment:	21/10/2021	
Date Inspected:	25/10/2021	Inspected At: Accord Auto Services Pte Ltd (Bukit Merah) BLK 1009 BUKIT MERAH LANE 3, #01-80 Singapore 159723
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Nov 2021)
Parts:	143	mitsubishi attrage 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMF3138G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH LAMP	Cut	480.00 FL	*337.00 FL
2	1		*REAR RH FENDER	Repair	780.00 FL	*- FL
3	1		*REAR RH FENDER SHIELD	Not Necessary	168.98 FL	*- FL
4	1		*REAR BUMPER	Crushed	720.50 FL	*720.50 FL
5	1		*REAR RH SIDE RETAINER LONG	Not Necessary	65.00 FL	*- FL
6	1		*REAR RH BUMPER SIDE RETAINER SHORT	Broken	55.00 FL	*28.00 FL
7	1		*SET REAR BUMPER CLIPS	Necessary	35.00 FS	*30.00 FS
8	2		*SET REAR FENDER SHIELD CLIPS	Not Necessary	60.00 FS	*- FS
9	1		*SET REAR BUMPER LOWER SPOILER	Repair	720.00 FS	*- FS
					Sub Total (\$\$)	3,084.48
					- List Item Discount on L Items 15.00/20.00% (\$\$)	340.42
					Total Parts (\$\$)	2,744.06
						898.40

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING TO ALL AFFECTED AREAS	New	600.00	600.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGES PARTS TO KNOCK,JACK,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	900.00	300.00
3	CHECK WIRING SYSTEM & LIGHT	New	100.00	30.00
4	ANTI RUST TREATMENT	New	100.00	30.00
5	TO REMOVE/REFIX INNER COMPARTMENT & CARPET TO FACILITATE REPAIR	New	280.00	0.00
6	TO REMOVE/REFIX REAR BUMPER SENSOR	New	150.00	30.00
Gross Labour Cost (\$\$)			2,130.00	990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >