

**LKK Auto Consultants**  
**#01-25 Paya Ubi Industrial Park, 51**  
**Ubi Avenue 1**  
**408933**

**Insurer Reference:**  
**Repairer Reference: CK140598**  
**Date calculated: 22/11/2021 11:03 AM**

**Full Report**  
**Registration: SJP4291Y**  
**Printed: 22/11/2021 11:04 AM**

### Summary Information

---

#### Claim

Location:	Singapore (SG)	Work Provider:	ERGO Insurance Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:		Date of Incident:	30/03/21
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

### Vehicle Details

---

#### Vehicle

Manufacturer:	mitsubishi
Model:	LANCER (CY,CX,CZ)
Sub Model:	GLS
Model Sheet Number:	32 39 09
Registration:	SJP4291Y
VIN number:	JMYSRCY2A9U004079
Odometer:	

#### Model Specs

FROM 04/2009	FOG LAMPS	RADIAT GRILLE SPORT	4-DOOR SALOON
FRONT SKIRT	TWO COAT METALLIC	PREPARE OFF VEHICLE	

### Vehicle Condition


---

#### Vehicle Status

Pre-Accident Damage:  
Date of Inspection:

#### Damage Areas

**All** ☐  
**Underbody** ☐



## Labour

		Time Base 10 WU/h	Price = 45.00 SGD/h	
Code	Description		WU	Price SGD
NO NUMBER	PREPARATION TIME		2.0	9.00
514110 00	R + R FRONT BUMPER		8.0	36.00
NO NUMBER	RENEW FRONT BUMPER (REMOVED)		12.0	54.00
	INCLUDES: R + R FOG LAMPS AND NECESSARY ATTACHED PARTS			
0287	L/F BUMPER BRACKET CHECK			
0288	R/F BUMPER BRACKET CHECK			
0345	CTR BUMPER BRACKET CHECK			
0561	L/F HEADLAMP CPL CHECK			
0562	R/F HEADLAMP CPL CHECK			
<b>Labour Cost</b>		<b>Hrs</b>	<b>WU</b>	
<b>Panel / Mechanical Labour</b>		<b>2.20</b>	<b>22.0</b>	<b>99.00</b>
<b>Total of Labour</b>				<b>99.00</b>

## Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC		WU	Price SGD
	FRONT BUMPER COVER NEW PART PAINT K1R		13.0	
	L/F SPOILER SURFACE PAINT PLAST.		4.0	
	R/F SPOILER SURFACE PAINT PLAST.		4.0	

### Paint Material Per Part

Code	Description	Price SGD
0283	FRONT BUMPER COVER NEW PART PAINT K1R	64.94
0393	L/F SPOILER SURFACE PAINT PLAST.	5.12
0394	R/F SPOILER SURFACE PAINT PLAST.	5.12

<b>Labour Cost - Paint</b>		<b>Hrs</b>	<b>WU</b>	<b>Price SGD</b>
Factor	45.00 SGD/h			
Time Paint			21.0	
Preparation Comp. Work Plastic		1.50	15.0	67.50
<b>Total</b>	<b>10 WU/h</b>	<b>3.60</b>	<b>36.0</b>	<b>162.00</b>

<b>Material Cost - Paint</b>	<b>Price SGD</b>
New Part Painting - Plastic K1R	64.94
Surface Painting Plastic	10.24
Material-constant Plastic	28.60
<b>Total</b>	<b>103.78</b>

## Spare Parts

prices as at 2015-06-01

Code	Description	Part Number	Part Source	Price SGD
0283	FRONT BUMPER COVER	6400D159	Original	420.00
f: OEM Parts	<b>Savings</b>			<b>0.00</b>
n: Non-OEM Parts	<b>Subtotal</b>			<b>420.00</b>
u: Used parts	<b>Addition(+10.00%)</b>			<b>42.00</b>
	<b>Total</b>			<b>462.00</b>

### Extras

Code	Description	Price SGD
1000	AUDATEX FEE SN	40.00*
	<b>Total Extras</b>	<b>40.00</b>

### Final Calculation

	SGD	SGD
<b>Parts</b>	420.00	
Addition(+10.00%)	42.00	
<b>Total Parts</b>		<b>462.00</b>
<b>Labour Time Base 10 WU/h</b>		
Total 22.0 WU X 45.00 SGD/h	99.00	
<b>Total of Labour</b>		<b>99.00</b>
<b>Total Of Extras</b>		<b>40.00</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 36.0 WU X 45.00 SGD/h	162.00	
Material Cost	103.78	
<b>Total Paint Including Material</b>		<b>265.78</b>
<b>Repair Cost Excludes GST</b>		<b>866.78</b>
GST (+7.0%)		<b>60.67</b>
<b>Repair Cost Included GST</b>		<b>927.45</b>

### Comments

\* - USER SUPPLIED DATA  
 NN - NO MANUFACTURERS CODE EXISTS  
 ) - WU PARTIAL INCL IN OTHER POSITIONS

### Assessment Note

No assessment notes entered.