

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG21010809/UTF3N2**Date:** 03/11/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700034729
Claimant Vehicle No :	SKL4002A	Insured Vehicle No :	SLS301P
Date of Loss:	18/10/2021	Nature of Claim:	TP
		Claim No:	8155134161SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKL4002A		
Make & Model:	PORSCHE CAYENNE, 3.6 V6 E5 TIPTRONIC (A)	Engine No:	D06462
Reg. Date:	14/01/2013 (Man. Year: 2012)	Chassis No:	WP1ZZZ92ZDLA05699
Colour:	Black	Odometer:	158335 km
Engine Capacity:	3598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/50ZR19	Rear Tyre Size:	275/50ZR19
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,739.00	4,126.50	12,612.50	75.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	2,030.00	1,170.00	36.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,939.00	6,156.50	13,782.50	69.12
Approved Total (Overridden) (S\$)		4,900.00		
Nett Amount (S\$)	19,939.00	4,900.00	15,039.00	75.43

INSPECTION

Date of Assignment:	21/10/2021		
Date Inspected:	22/10/2021	Inspected At:	Autobay Pte Ltd (kaki Bukit) (HQ) 1 KAKI BUKIT AVE 6, #02-11 Singapore 417883
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Repair	2,251.00 FL	*- FL
2	1		*FRONT FENDER LH INNER SHIELD	Not Necessary	562.00 FL	*- FL
3	1		*FRONT FENDER LH GARNISH	Repair	473.00 FL	*- FL
4	1		*FRONT FENDER LH PROTECTOR	Grazed	321.00 FL	*321.00 FL
5	1		*FRONT DOOR LH	Dented/Bent	3,260.00 FL	*2,950.00 FL
6	1		*FRONT DOOR LH GARNISH	Warped/Necessary	358.00 FL	*358.00 FL
7	1		*FRONT DOOR LH PROTECTOR	Not Necessary	758.00 FL	*- FL
8	1		*FRONT DOOR LH RUBBER	Necessary	459.00 FL	*355.00 FL
9	1		*FRONT DOOR LH OUTER MOULDING	Not Necessary	476.00 FL	*- FL
10	1		*FRONT DOOR STICKER	Necessary	128.00 FL	*128.00 FL
11	1		*REAR DOOR LH	Repair	3,260.00 FL	*- FL
12	1		*REAR FENDER LH INNER SHIELD	Not Necessary	562.00 FL	*- FL
13	1		*REAR FENDER LH PROTECTOR	Grazed	473.00 FL	*473.00 FL
14	1		*REAR BUMPER	Not Necessary	1,817.00 FL	*- FL
15	4		*REAR BUMPER SIDE RETAINER	Not Necessary	552.00 FL	*- FL
16	1		*REAR ALLOY WHEEL RH	Repair	1,950.00 FS	*- FS
17	1		*REAR TYRE RH	Serviceable	650.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	18,310.00	4,585.00
- List Item Discount on L Items 10.00/10.00% (\$)	1,571.00	458.50
Total Parts (\$)	16,739.00	4,126.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECKING ELECTRICAL WIRING AND CHECK FUNCTIONS	New	90.00	20.00
2	TO REMOVE,REFIX REAR RH RIM AND PERFORM TYRE BALANCING	New	50.00	50.00
3	TO REMOVE,REFIX FRONT LH DOOR AND COMPONENTS AND REPLACE DOOR,CHECK ALIGNMENT	New	380.00	100.00
4	TO CONDUCT COMPUTERIZED 4-WHEEL ALIGNMENT	New	180.00	60.00
5	TO RESPRAY UNDERCOATING/RUST PROOFING	New	100.00	50.00
6	TO RESPRAY PAINTING & ETC	New	1,450.00	1,000.00
7	LABOUR CHARGE TO PANEL BEATING ETC AND REPLACING ABOVE PARTS	New	950.00	750.00
			Gross Labour Cost (\$)	3,200.00
				2,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >