

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	SOMPO INSURAN	CE SINGAPORE PL	Ref:	CS/SMO21010811/Uvf3n2	
	50 RAFFLES PLAC SINGAPORE LAND	CE #03-03 D TOWERSINGAPORE 048623	Date:	16/11/2021	
			Code:	SMO	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XE 2785U	Veh. Inspected	XE 6868M	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	CMTD2103133/AGC	Excess (\$)	0.00	
	Assign From	GRACE TEO	Assign Date	21/10/2021	
2.	2. Vehicle Particulars & Condition				
	Make & Model	MITSUBISHI FUSO FV51 (A)	c.c	11967	
	Engine No.	HIDDEN	Year of Reg.	2014	
	Chassis No.	FV51SSA10050	Colour	BLUE	
	Odometer	510836 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	295/80 R22.5	SAFE KING	6 mm	
	L/H Front Tyre	295/80 R22.5	SAFE KING	6 mm	
	R/H Rear Tyre	295/80 R22.5 (D/D)	SAFE KING	6/6 6/6 mm	
	L/H Rear Tyre	295/80 R22.5 (D/D)	SAFE KING	6/6 6/6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	20/10/2021	Inspection Date	26/10/2021	
	Survey held at	FASTECH AUTO PTE LTD	-		
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days			