

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / P / W / TP / RES / OD / RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

Site Insp (\$

Interview (\$

Tech. Invs (\$

Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

Photos

Others

TOTAL

Veh No: SME 4433C Yr Regn: 28/9/18Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or WMake: Mer Benz C200 cc 1991Colour: Black A/C: Insured / Std / NI / NASp. Reading: 37035 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: Insured / Jammed / Leaked / Burnt orBrake: Insured / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

red:5197.70;82%

Reer bumper No stock agree repair
Confirmed P/2 @ 1100 with M.R.T.P.



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Budget Direct Insured's Veh No : SML4516K

Date of Accident : 14 October 2021

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Miss Nurhanisah Binte Ali

Date : 21 October 2021

not Authorized
27/10/21
P/P \$1100
3 days
when photo taken

Estimate To Repair SME4433C - Mercedes Benz C200 Auto

Chassis No : WDD2050422R339391

S/No	Quantity	Description	Amount
NETT ITEMS			
01	1 pc	tailgate lid B160 Badge <i>11</i>	\$ 80.00 <i>X</i>
02	1 pc	tailgate lid centre logo star badge <i>11</i>	\$ 50.00 <i>X</i>
03	1 pc	rear bumper <i>R</i>	\$ 1,610.00 <i>X</i>
04	2 ps	rear bumper chrome moulding @ \$125.00 <i>NZ</i>	\$ 250.00 <i>X</i>
05	2 ps	rear bumper reflector @ \$195.00 <i>NZ</i>	\$ 390.00 <i>X</i>
06	1 pc	rear bumper lower diffuser <i>3 days</i>	\$ 200.00 <i>X</i>
07	2 ps	rear bumper side retainer @ \$60.00 <i>11</i>	\$ 120.00 <i>X</i>
08	1 pc	rear bumper top skid plate <i>NZ</i>	\$ 285.00 <i>X</i>
09	4 ps	rear bumper clip @ \$7.00 <i>11</i>	\$ 28.00 <i>X</i>
10	1 pc	rear bumper reinforcement <i>11</i>	\$ 660.00 <i>X</i>
11	1 pc	rear end panel <i>N</i>	\$ 780.00 <i>X</i>
		Less 10 %	\$ 4,453.00
			\$ 445.30
			\$ 4,007.70
SPECIAL NETT ITEMS			
12	1 set	rear bumper parking sensor <i>NZ</i>	\$ 550.00 <i>X</i>
			\$ 550.00
LABOUR & MISC. CHARGES			
01		To reinstall of rear bumper parking sensor.	\$ 120.00 <i>X</i>
02		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 60.00 <i>X</i>
03		To check electrical lighting concerned.	\$ 60.00 <i>20</i>
04		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 750.00 <i>500</i>
05		Putty and spray painting of the affected portion.	\$ 750.00 <i>400</i>
			\$ 1,740.00
		Total	\$ 6,297.70
			<i>P-200</i> <i>102</i> <i>180</i>
			<i>P-200</i> <i>102</i> <i>180</i> <i>920</i> <i>1100</i>

UKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To survey damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: