

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21010835/AEA3Q2**Date:** 05/04/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900058014
Claimant Vehicle No :	SMR1189J	Insured Vehicle No :	SMJ3814S
Date of Loss:	20/10/2021	Nature of Claim:	TP
		Claim No:	3846708141SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR1189J		
Make & Model:	AUDI A1 SPORTBACK, 1.0 Advanced TFSI S-tronic (A)	Engine No:	DKJ045343
Reg. Date:	19/12/2019 (Man. Year: 2019)	Chassis No:	WAUZZZGB7LR006433
Colour:	Black	Odometer:	27691 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R16	Rear Tyre Size:	195/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,942.00	782.40	10,159.60	92.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,062.00	2,352.00	2,710.00	53.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,004.00	3,134.40	12,869.60	80.41
+ GST 7.00/7.00% (S\$)	1,120.28	219.41	900.87	80.41
Nett Amount (S\$)	17,124.28	3,353.81	13,770.47	80.41
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,555.81		

INSPECTION

Date of Assignment:	26/10/2021		
Date Inspected:	26/10/2021	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,634.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	137.00 FS	*- FS
3	1		*FRONT BUMPER SPOILER	Not Necessary	100.00 FS	*- FS
4	1		*FRONT BUMPER AIR GRILLE -LH	Not Necessary	211.00 FS	*- FS
5	1		*FRONT BUMPER GRILLE -CENTER	Not Necessary	196.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTER	Not Necessary	167.00 FS	*- FS
7	1		*RADIATOR GRILLE	Not Necessary	926.00 FS	*- FS
8	1		*RADIATOR GRILLE CLOSING ELEMENT	Not Necessary	161.00 FS	*- FS
9	1		*FRONT BUMPER FOAM PIECE	Not Necessary	118.00 FS	*- FS
10	1		*FRONT BUMPER CARRIER	Not Necessary	723.00 FS	*- FS
11	1		*FRONT BUMPER TOP COVER	Not Necessary	123.00 FS	*- FS
12	1		*FRONT BUMPER GUIDE SECTION -LH	Not Necessary	107.00 FS	*- FS
13	1		*FRONT BUMPER GUIDE PROFILE -LH	Not Necessary	36.00 FS	*- FS
14	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
15	1		*A/C STICKER	Not Necessary	19.00 FS	*- FS
16	1		*HORN	Not Necessary	137.00 FS	*- FS
17	1		*HORN BRACKET	Not Necessary	41.00 FS	*- FS
18	1		*FRONT FENDER -LH	Buckled	978.00 FS	*782.40 FS
19	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	116.00 FS	*- FS
20	1		*FRONT FENDER BRACE -LH	Not Necessary	54.00 FS	*- FS
21	1		*FRONT WHEEL HOUSING LINER (NPA)	Not Necessary	0.00 FS	*- FS
22	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	69.00 FS	*- FS
23	1		*FRONT FENDER BRACE	Not Necessary	76.00 FS	*- FS
24	1		*HEADLIGHT -LH	Not Necessary	4,288.00 FS	*- FS
25	1		*HEADLIGHT LIFT CYLINDER -LH	Not Necessary	142.00 FS	*- FS
26	1		*HEADLIGHT LIFT CYLINDER HOSE	Not Necessary	59.00 FS	*- FS
27	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
28	1		*SUNDRIES	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **10,942.00** **782.40**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE CHECK TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER ,LHS FRONT FENDER AND LHS HEADLIGHT RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,000.00	1,100.00
5	TO REAPPLY HEADLIGHT PROTECTION FILM (BY OWNDER)	New	60.00	60.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			5,062.00	2,352.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >