

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI21010837/ATF3N2**Date:** 20/12/2021REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : GBH9533D **Insured Vehicle No :** XD5882H
 Date of Loss: 09/10/2021 Nature of Claim: TP Claim No: CDMFG21002034

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH9533D**
 Make & Model: ISUZU NHR87AUE4AA, 1.9 D (M) Engine No: RZ4E10D925
 Reg. Date: 01/11/2018 (Man. Year: 2018) Chassis No: JAANHR87EJ7100099
 Colour: Blue Odometer: 121216 km
 Engine Capacity: 1898 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/75R15 Rear Tyre Size: 165R13
 Front Left Side: Bridgestone 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,345.54	2,442.12	4,903.42	66.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	1,330.00	990.00	42.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,665.54	3,772.12	5,893.42	60.97
Approved Total (Overridden) (S\$)		3,000.00		
(S\$)	9,665.54	3,000.00	6,665.54	68.96
+ GST 7.00/7.00% (S\$)	676.59	210.00	466.59	68.96
Nett Amount (S\$)	10,342.13	3,210.00	7,132.13	68.96

INSPECTION

Date of Assignment: 21/10/2021
 Date Inspected: 22/10/2021 Inspected At: Ryder Auto Pte Ltd (HQ)
 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit
 Singapore 417921
 Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 20 Dec 2021)	
Parts:	N/A	ISUZU NHR87AUE4AA 1.9 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH9533D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT N/S CORNER PANEL	Cracked	310.00 FL	*310.00 FL
2	1		*FRONT N/S DOOR PILLAR (OUTER)	Repair	1,960.00 FL	*- FL
3	1		*FRONT N/S DOOR	Distorted	1,320.00 FL	*1,150.00 FL
4	2		*FRONT N/S DOOR STRIKER	Not Necessary	100.00 FL	*- FL
5	1		*FRONT N/S DOOR HINGES (UPPER & LOWER)	Not Necessary	272.00 FL	*- FL
6	1		*FRONT N/S DOOR LOCK (INNER)	Damaged	142.00 FL	*142.00 FL
7	1		*FRONT N/S DOOR WINDOW SEAL (OUTER)	Missing	112.50 FL	*112.50 FL
8	1		*FRONT N/S DOOR WINDOW REGULATOR	Not Necessary	153.20 FL	*- FL
9	1		*FRONT N/S DOOR WINDOW REGULATOR MOTOR	Not Necessary	286.60 FL	*- FL
10	1		*FRONT N/S DOOR WINDOW CHANNEL	Not Necessary	110.00 FL	*- FL
11	1		*FRONT N/S DOOR WINDOW CHANNEL BRACKET	Not Necessary	30.00 FL	*- FL
12	1		*FRONT N/S DOOR WINDOW INNER BOARD	Cut	640.00 FL	*425.00 FL
13	1		*FRONT N/S DOOR WEATHERSTRIP	Not Necessary	186.50 FL	*- FL
14	1		*FRONT WINDSCREEN MOULDING (UPPER & LOWER)	Not Necessary	310.00 FL	*- FL
15	1		*FRONT N/S DOOR HANDLE UPPER	Not Necessary	30.00 FL	*- FL
16	1		*FRONT N/S DOOR HANDLE LOWER	Not Necessary	31.20 FL	*- FL
17	1		*FRONT N/S B DOOR PILLAR	Not Necessary	1,455.40 FL	*- FL
18	1		*FRONT N/S DOOR GLASS	Shattered	340.60 FL	*340.60 FL
19	1		*FRONT N/S DOOR WINDOW SEAL (INNER)	Necessary	122.40 FL	*122.40 FL
20	1		*FRONT N/S DOOR COMPANY STICKER	Necessary	300.00 FS	*200.00 FS
21	12		*FRONT N/S DOOR WINDOW INNER BOARD CLIPS	Necessary	60.00 FS	*30.00 FS
22	2		*FRONT WINDSCREEN MOULDING (O/S & N/S)	Not Necessary	200.00 FS	*- FS
23	1		*FRONT WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,532.40	2,832.50
- List Item Discount on L Items 15.00/15.00% (\$\$)	1,186.86	390.38
Total Parts (\$\$)	7,345.54	2,442.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE DAMAGED PARTS,STRAIGHTEN & WELDING	New	1,000.00	600.00
2	TO SPRAY PAINTING	New	800.00	600.00
3	TO REMOVE & REFIT WINDSCREEN	New	120.00	0.00
4	TO REMOVE & REPLACE FRONT N/S DOOR	New	100.00	0.00
5	TO REMOVE AND REFIT MECHANISM & MOTOR	New	50.00	50.00
6	TO RE-SET ELECTRICAL SYSTEM	New	150.00	0.00
7	TO CHECK WIRING	New	50.00	30.00
8	TO RE-SEAL ANTI RUST	New	50.00	50.00
			Gross Labour Cost (\$)	2,320.00
				1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >