



2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417927

Email: ryderautoworkshop@gmail.com  
Tel: 67418277 Fax: 67468277

**ESTIMATE OF REPAIR**

Veh# : GBH9533D

Accident Date : 9/10/2021

Location : PIONEER RD TOWARDS PINEERING RD NORTH

TP Ergo  
Denise.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Model: ISUZU NHR87AUE4AA MT  
Signature: \_\_\_\_\_  
Date: 1/11/2018

3P: XD5882H(ERGO)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front n/s corner panel <i>crack</i>	310.00	✓	
2	1 pc	Front n/s door pillar <i>Repair</i>	1,960.00	+	
3	1 pc	Front n/s door <i>Distorted</i>	1,320.00	+	
4	1 pc	Front n/s door company sticker <i>new</i>		300.00	200
5	2 pcs	Front n/s door striker <i>new</i>	100.00	+	
6	1 pc	Front n/s door hinges (upper & lower) <i>new</i>	272.00	+	
7	1 pc	Front n/s door lock (inner) <i>Repair</i>	142.00	✓	
8	1 pc	Front n/s door window seal (outer) <i>missing</i>	112.50	✓	
9	1 pc	Front n/s door window regulator <i>new</i>	153.20	+	
10	1 pc	Front n/s door window regulator motor <i>new</i>	286.60	+	
11	1 pc	Front n/s door window channel <i>new</i>	110.00	+	
12	1 pc	Front n/s door window channel bracket <i>new</i>	30.00	+	
13	1 pc	Front n/s door window inner board <i>at</i>	640.00	+	
14	12 pcs	Front n/s door window inner board clips <i>new</i>		60.00	
15	1 pc	Front n/s door weatherstrip <i>new</i>	186.50	+	
16	1 pc	Front windscreen moulding (upper & lower) <i>new</i>	310.00	+	
17	1 pc	Front windscreen moulding (o/s & n/s) <i>new</i>		200.00	+
18	1 pc	Front windscreen sealant <i>new</i>		60.00	+
19	1pc	Front n/s door handle upper <i>new</i>	30.00	+	
20	1pc	Front n/s door handle lower <i>new</i>	31.20	+	
21	1pc	Front n/s B door pillar <i>new</i>	1,455.40	+	
		Sub Total:	7,449.40	620.00	0.00
			15%	0%	0%
		After Less %:	6,331.99	620.00	0.00
		<b>Labour</b>			
1		To dismantle damaged parts, straighten & welding.		1,000.00	600
2		To spray painting.		800.00	600
3		To remove & refit windscreen		120.00	+
4		To remove & replace front n/s door. <i>Repair</i>		100.00	80 X
5		To remove and refit mechanism & motor		50.00	✓
6		To re set electrical system.		150.00	80 X
7		To check wiring.		50.00	30
8		To re seal anti rust.		50.00	✓
		Sub Total:		2,320.00	
		Total:		9,271.99	
		After less 20%		7417.592	

2139.50 S.N: 230  
1818.57

1330

*Chan*  
Chan San Choon  
Director  
DipEng, AAE MIMI,MSAE(Aust)

Supplementary: 393.55  
Total: 3772.12  
A/S: 3K  
Adrian  
w/s 22/10/21  
0.5 Days



AL 8778 1999  
GBH9533D ESTIMATE Pg 1



2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921  
 Email: ryderautoworkshop@gmail.com  
 Tel: 67418277 Fax: 67468277

## SUPPLEMENTARY ESTIMATE OF REPAIR

Veh# : GBH9533D

Model: ISUZU NHR87AUE4AA MT

Accident Date : 9/10/2021

1/11/2018

Location : PIONEER RD TOWARDS PINEERING RD NORTH

3P: XD5882H(ERGO)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front n/s door glass <i>Shattered</i>	340.60	✓	
2	1 pc	Front n/s door window seal (inner) <i>nc</i>	122.40	✓	
		Sub Total:	463.00	0.00	0.00
			15%	0%	0%
		After Less %:	<b>393.55</b>	<b>0.00</b>	<b>0.00</b>
		Total:		<b>393.55</b>	
		After less 20%		<b>314.84</b>	

*Chan*

Chan San Choon  
 Director  
 DipEng, AAE MIMI,MSAE(Aust)

*Adrian Lj*  
*25/10/21.*



**AL 8778 1999**  
 24 hr accident call



*Supplementary: 393.55*