

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21010845/DGA3Q2**Date:** 14/06/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SLZ3940M	Insured Vehicle No :	SLN4526H
Date of Loss:	20/10/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0004652

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ3940M		
Make & Model:	TOYOTA PRIUS HYBRID ALPHA, 1.8 S CVT (A)	Engine No:	2ZR0A83374
Reg. Date:	30/04/2018 (Man. Year: 2018)	Chassis No:	ZVW400028058
Colour:	Blue	Odometer:	186943 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Firenza 5 mm	Rear Left Side:	Firenza 5 mm
Front Right Side:	Firenza 5 mm	Rear Right Side:	Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,902.47	713.00	15,189.47	95.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,550.00	640.00	5,910.00	90.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,452.47	1,353.00	21,099.47	93.97
Approved Total (Overridden) (S\$)		1,050.00		
(S\$)	22,452.47	1,050.00	21,402.47	95.32
+ GST 7.00/7.00% (S\$)	1,571.67	73.50	1,498.17	95.32
Nett Amount (S\$)	24,024.14	1,123.50	22,900.64	95.32
+ Car Rental (4.0 x S\$92.00/day) (S\$)		368.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,498.95		
Global Sum Settlement (S\$)		1,450.00		

INSPECTION

Date of Assignment:	22/10/2021	
Date Inspected:	22/10/2021 Inspected At:	JWG International Pte Ltd (HQ) Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint Singapore 568047
Estimated Period of Repair:	2.0 days	

Adjuster: BRYAN TANI**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Jun 2022)

Parts: M1-MPV TOYOTA PRIUS HYBRID ALPHA 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLZ3940M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Not Necessary	1,659.20 FL	*- FL
2	1		*TAILGATE INNER TRIM BOARD	Not Necessary	525.50 FL	*- FL
3	1		*TAILGATE CENTER MOULDING	Not Necessary	495.79 FL	*- FL
4	1		*TAILGATE TOYOTA LOGO	Not Necessary	72.50 FL	*- FL
5	1		*TAILGATE PRIUS PLUS EMBLEM	Not Necessary	65.90 FL	*- FL
6	1		*TAILGATE HYBRID SUNERGY EMBLEM	Not Necessary	79.62 FL	*- FL
7	1		*TAILGATE SWITCH	Not Necessary	352.90 FL	*- FL
8	1		*TAILGATE LOCK	Not Necessary	461.60 FL	*- FL
9	1		*TAILGATE WEATHERSTRIP	Not Necessary	399.82 FL	*- FL
10	2		*TAIL LAMP LH/RH	Not Necessary	1,203.80 FL	*- FL
11	2		*TAIL LAMP PANEL LH/RH	Not Necessary	679.60 FL	*- FL
12	2		*TAIL LAMP LOWER BRACKET LH/RH	Not Necessary	418.80 FL	*- FL
13	1		*REAR BUMPER	Distorted / Mtg Cracked	1,030.59 FL	*524.00 FL
14	1		*SET REAR BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
15	2		*REAR BUMPER SIDE RETAINER L+R	Serviceable	288.84 FL	*- FL
16	2		*REAR BUMPER REFLECTOR LH/RH	Not Necessary	218.66 FL	*- FL
17	1		*REAR END PANEL	Not Necessary	880.80 FL	*- FL
18	1		*REAR END PANEL TOP GARNISH	Not Necessary	332.40 FL	*- FL
19	1		*SPARE WHEEL PANEL	Not Necessary	1,219.48 FL	*- FL
20	2		*SPARE WHEEL QUARTER PANEL LH/RH	Not Necessary	1,397.48 FL	*- FL
21	1		*SPARE WHEEL PANEL TOP BOARD	Not Necessary	412.99 FL	*- FL
22	1		*SPARE WHEEL PANEL TOOL BOX	Not Necessary	519.80 FL	*- FL
23	2		*REAR FENDER LH /RH	Not Necessary	3,695.72 FL	*- FL
24	2		*REAR FENDER INNER TRIM LH /RH	Not Necessary	1,764.84 FL	*- FL
25	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
26	1		*REVERSE SENSOR	Damaged	400.00 FS	*220.00 FS
27	1		*TAIL LAMP SEALANT	Not Necessary	60.00 FS	*- FS
28	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
29	1		*REVERSE CAMERA	Not Necessary	500.00 FS	*- FS
30	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
31	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
32	1		*REAR BUMPER TOP GARNISH	Necessary	800.00 FS	*80.00 FS
33	1		*TAILGATE CENTER MOULDING CLIPS	Not Necessary	50.00 FS	*- FS
34	1		*TAILGATE INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
35	1		*REAR BUMPER CLIPS	Repeated	50.00 FS	*- FS
36	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	20,446.63	844.00
- List Item Discount on L Items 25.00/25.00% (S\$)	4,544.16	131.00
Total Parts (S\$)	15,902.47	713.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	300.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	300.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	300.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	0.00
5	TO RNR REAR BOOT MECHANISM TO ASSIST WORK LOAD	New	200.00	0.00
6	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	New	250.00	0.00
7	TO RNR TAILGATE WINDSCREEN TO ASSIST WORK LOAD	New	300.00	0.00
8	TO RNR REAR FENDER QUARTER GLASS TO FACILITATE REPAIRS	New	400.00	0.00
9	TO RNR REVERSE SENSOR & REVERSE CAMERA	New	300.00	40.00
10	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	0.00
11	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (S\$)			6,550.00	640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >