

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMK 947G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT DOOR (RH) (CONSISTENT)	BENT	1,718.90	1,242.30
1	FRONT DOOR HINGE TOP RH (CONSISTENT)	TO REPAIR SEE LABOUR	153.50	-
1	FRONT DOOR HINGE BOTTOM RH (CONSISTENT)	DISTORTED	135.20	135.20
1	FRONT DOOR REGULATOR (RH) (CONSISTENT)	SERVICEABLE	578.90	-
1	FRONT DOOR REGULATOR MOTOR (RH) (CONSISTENT)	SERVICEABLE	789.10	-
1	FRONT DOOR CHECKER RH (CONSISTENT)	DISTORTED	265.00	265.00
1	RIGHT FRONT DOOR OUTER MOULDING (CONSISTENT)	SERVICEABLE	180.00	-
1	FRONT DOOR INNER LOCK (RH) (CONSISTENT)	TO REPAIR SEE LABOUR	364.20	-
1	WING MIRROR (RH) (CONSISTENT)	SERVICEABLE	1,217.90	-
1	FRONT FENDER (RH) (CONSISTENT)	BENT	978.10	978.10
1	FRONT FENDER INNER SHIELD (RH) (CONSISTENT)	SERVICEABLE	148.00	-
1	SIDE SKIRT (RH) (CONSISTENT)	MTG DISTORTED	789.10	755.10
	LESS 10% DISCOUNT		-	-337.57
			7,317.90	3,038.13
	SPECIAL NETT ITEMS			
1	FRONT DOOR RUBBER (RH) (\$266.70) (50%) (SN) (CONSISTENT)	СИТ	289.50	133.35
10	FRONT FENDER INNER SHIELD CLIPS @\$3.50 (SN) (CONSISTENT)	NOT NECESSARY	35.00	-
			324.50	133.35
	<u>LABOUR</u>			
	LABOUR TO REPLACE ABOVE PARTS ,PANEL BEAT ,REPAIR & RE-ALIGN DAMAGE PARTS.INCLUSIVE OF THE REPAIR OF FRONT DOOR HINGE TOP RH AND FRONT DOOR INNER LOCK (RH) .		1,000.00	500.00
	TO PUTTY & SPRAY PAINT FRONT DOOR RIGHT ,FRONT FENDER RIGHT ,WING MIRROR COVER RIGHT ,SIDESKIRT RIGHT & OTHER AFFECTED AREAS .		1,700.00	800.00
			2,700.00	1,300.00
	GRAND TOTAL		10,342.40	4,471.48

Report Ref No. CC4/ASM21010846/Krs3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		3,500.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CC4/ASM21010846/Krs3q2

**KONG SENG CHEONG** 

**Licensed Appraiser**