



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CYNTHIA			Ref: CC4/ASM21010846/Krs3q2 Date: 13/12/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 8559L	Veh. Inspected	SMK 947G	
Policy No.	P2419140	Coverage (\$)	0.00	
Claim No.	S1M03KFO	Excess (\$)	0.00	
Assign From		Assign Date	22/10/2021	
2. Vehicle Particulars & Condition				
Make & Model	LEXUS IS250 (A)	c.c	2500	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JTHBK262502094998	Colour	WHITE	
Odometer	123923 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	GOODYEAR	7 mm	
L/H Front Tyre	225/45 R17	GOODYEAR	7 mm	
R/H Rear Tyre	225/45 R17	GOODYEAR	7 mm	
L/H Rear Tyre	225/45 R17	GOODYEAR	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/10/2021	Inspection Date	22/10/2021	
Survey held at	BODYFIX NO 10 ANG MO KIO INDUSTRIAL PARK 2A #04-06 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	