

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010854/TTY3N2**Date:** 23/02/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00039982100	
Claimant Vehicle No :	SNA9274X	Insured Vehicle No :	GBL2158D	
Date of Loss:	20/10/2021	Nature of Claim:	TP	Claim No: SNM21D206012/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNA9274X		Engine No:	LEB5972530
Make & Model:	HONDA VEZEL, 1.5 (A)		Chassis No:	RU31272512
Reg. Date:	23/07/2021 (Man. Year: 2018)		Odometer:	23838 km
Colour:	Grey			
Engine Capacity:	1496 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,835.36	4,891.76	1,943.60	28.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,810.00	1,420.00	390.00	21.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	8,645.36	6,311.76	2,333.60	26.99
+ GST 7.00/7.00% (\$\$)	605.18	441.82	163.36	26.99
Nett Amount (\$\$)	9,250.54	6,753.58	2,496.96	26.99

INSPECTION

Date of Assignment:	22/10/2021		
Date Inspected:	22/10/2021	Inspected At:	SIN MING DRIVE #08-09 SIN MING AUTO CITY REPAIRER: VIN'S MOTOR PTE LTD
Estimated Period of Repair:	6.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Feb 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNA9274X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,100.90 FL	*953.00 FL
2	1		*REAR TAILGATE GLASS MOULDING	Necessary	120.30 FL	*120.30 FL
3	1		*REAR TAILGATE OUTER GARNISH	Deformed	225.70 FL	*193.60 FL
4	1		*REAR TAILGATE OUTER GARNISH EMBLEM	Necessary	20.70 FL	*20.70 FL
5	1		*REAR TAILGATE VEZEL EMBLEM	Necessary	43.20 FL	*43.20 FL
6	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	75.50 FL	*75.50 FL
7	1		*REAR TAILGATE RH REFLECTOR	Cut	424.30 FL	*424.30 FL
8	1		*REAR TAILGATE LH REFLECTOR	Cut	424.30 FL	*424.30 FL
9	1		*REAR TAILGATE RUBBER	Twisted	101.30 FL	*101.30 FL
10	1		*REAR TAILGATE INNER TRIMBOARD	Cracked	153.40 FL	*153.40 FL
11	1		*REAR TAILGATE PULL HANDLE COVER	Not Necessary	36.20 FL	*- FL
12	1		*REAR RH TAILLAMP	Cut	586.70 FL	*474.60 FL
13	1		*REAR LH TAILLAMP	Cut	586.70 FL	*474.60 FL
14	1		*REAR BUMPER	Deformed	829.60 FL	*751.00 FL
15	1		*REAR BUMPER RH REFLECTOR	Not Necessary	178.50 FL	*- FL
16	1		*REAR BUMPER LH REFLECTOR	Not Necessary	178.50 FL	*- FL
17	10		*REAR BUMPER CLIPS	Necessary	39.00 FL	*39.00 FL
18	1		*REAR BUMPER RH SIDE RETAINER	Not Necessary	17.50 FL	*- FL
19	1		*REAR BUMPER LH SIDE RETAINER	Not Necessary	17.50 FL	*- FL
20	1		*REAR BUMPER ANTENNA SENSOR	Cracked	68.10 FL	*68.10 FL
21	1		*REAR BUMPER BUZZLE SENSOR	Not Necessary	81.20 FL	*- FL
22	1		*REAR END PANEL	Repair	411.90 FL	*- FL
23	1		*REAR END PANEL TOP TRIM	Deformed	98.20 FL	*98.20 FL
24	1		*REAR SPARE TYRE TOP COVER	Not Necessary	430.30 FL	*- FL
25	1		*REAR LUGGAGE COMPARTMENT BOX	Cracked	243.20 FL	*243.20 FL
26	1		*REAR RH FENDER INNER TRIMBOARD	Deformed	320.10 FL	*320.10 FL
27	1		*REAR LH FENDER INNER TRIMBOARD	Not Necessary	320.10 FL	*- FL
28	1		*WIPER MOTOR	Bent	205.00 FL	*205.00 FL
29	1		*REAR TAILGATE REVERSE CAMERA	Distorted	380.00 FS	*280.00 FS
30	1		*REAR BUMPER PARKING SENSOR	Not Working	280.00 FS	*200.00 FS
31	1		*REAR WINDSCREEN GUM	Necessary	60.00 FS	*60.00 FS
32	1		*REAR NO PLATE	Not Necessary	40.00 FS	*- FS
33	1		*REAR TAILGATE LOCK	Bent	256.30 FL	*256.30 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,354.20	5,979.70
- List Item Discount on L Items 20.00/20.00% (S\$)	1,518.84	1,087.94
Total Parts (S\$)	6,835.36	4,891.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIX REAR WINDSCREEN	New	150.00	120.00
2	TO REPAIR REAR DAMAGES	New	780.00	600.00
3	TO SPRAY PAINTING	New	880.00	700.00
Gross Labour Cost (S\$)			1,810.00	1,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >