

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21010855/EVY3E2

Date: 22/12/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00096952000
Claimant Vehicle No: SDN6899M Insured Vehicle No: GBE357X
Date of Loss: 15/10/2021 Nature of Claim: TP Claim No: SNM21D205941/C01/CHEESC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDN6899M**
Make & Model: MASERATI LEVANTE, 3.0 GRANSFORT (A) Engine No: 495999
Reg. Date: 25/05/2021 (Man. Year: 2021) Chassis No: ZN6XU61C00X373233
Colour: Black Odometer: 13786 km
Engine Capacity: 2979 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/50 R19 Rear Tyre Size: 215/50 R19
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,645.35	17,832.37	7,812.98	30.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	28,150.00	11,380.00	16,770.00	59.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	53,795.35	29,212.37	24,582.98	45.70
+ GST 7.00/7.00% (S\$)	3,765.67	2,044.87	1,720.80	45.70
Nett Amount (S\$)	57,561.02	31,257.24	26,303.78	45.70

INSPECTION

Date of Assignment: 16/12/2021
Date Inspected: 28/10/2021 Inspected At: Tridente Automobili Pte Ltd (HQ)
30 Leng Kee Road #01-02
Singapore 159100
Estimated Period of Repair: 8.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Dec 2021)

Parts: 143 MASERATI LEVANTE 3.0 GRANSFORT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SDN6899M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY ITEMS	Necessary	150.00 FS	*75.00 FS
2	1		*REAR NUMBER PLATE	Necessary	80.00 FS	*80.00 FS
3	1		*REAR WINDSCREEN SOLAR FILM	Necessary	450.00 FS	*450.00 FS
4	1		*REAR BUMPER	Crushed	4,092.10 FS	*4,092.10 FS
5	1		*RH EXHAUST TERMINAL	Not Necessary	1,122.10 FS	*- FS
6	1		*LH EXHAUST TERMINAL	Dented	1,122.10 FS	*1,122.10 FS
7	1		*COVER	Necessary	199.50 FS	*199.50 FS
8	2		*ENERGY ABSORBING UNIT	Necessary	105.00 FS	*105.00 FS
9	12		*RIVET	Necessary	88.80 FS	*88.80 FS
10	1		*CENTRAL BRACKET	Bent	145.10 FS	*145.10 FS
11	1		*RH BUMPER BRACKET	Not Necessary	107.60 FS	*- FS
12	1		*REAR BUMPER LH BRACKET	Not Necessary	107.60 FS	*- FS
13	4		*SILICON RING	Necessary	95.52 FS	*95.52 FS
14	1		*LH REAR SENSOR HOUSING	Necessary	116.80 FS	*116.80 FS
15	1		*RH REAR SENSOR HOUSING	Necessary	116.80 FS	*116.80 FS
16	1		*LH REAR SENSOR HOUSING	Necessary	116.80 FS	*116.80 FS
17	1		*RH REAR SENSOR HOUSING	Necessary	116.80 FS	*116.80 FS
18	2		*RADIAL PARKING SENSOR	Not Necessary	750.60 FS	*- FS
19	1		*PIN (26PCS)	Necessary	310.70 FS	*310.70 FS
20	4		*WHEELHOUSE LINER ADHESIVE	Necessary	30.40 FS	*30.40 FS
21	10		*ADHESIVE TAPE	Necessary	69.00 FS	*69.00 FS
22	9		*SPECIAL NUT	Necessary	418.95 FS	*418.95 FS
23	1		*STRAP UREA TANK	Not Necessary	64.95 FS	*- FS
24	1		*LOWER REAR GUARD ASSEMBLY	Repair	1,220.40 FS	*- FS
25	1		*REAR CRASH-BOX CROSS MEMBER	Not Necessary	573.50 FS	*- FS
26	4		*RIVET	Necessary	26.60 FS	*26.60 FS
27	1		*LEVANTE HFA SENSOR	Not Necessary	846.36 FS	*- FS
28	2		*ECU BUY LBSS-LEFT BLIND SPOT	Not Necessary	2,347.38 FS	*- FS
29	4		*SCREW	Not Necessary	10.44 FS	*- FS
30	3		*SCREW	Not Necessary	13.50 FS	*- FS
31	3		*BRACKET	Not Necessary	7.95 FS	*- FS
32	1		*LOGO ON BOOT LID	Necessary	77.60 FS	*77.60 FS
33	1		*REAR BADGE Q4 M161	Necessary	45.20 FS	*45.20 FS
34	1		*REAR LIFTGATE	Dented	4,035.10 FS	*4,035.10 FS
35	1		*RUBBER FOR REAR LICENSE PLAT	Necessary	3.60 FS	*3.60 FS
36	2		*RIVET	Necessary	17.80 FS	*17.80 FS
37	1		*RH REAR SPOILER	Necessary	682.40 FS	*682.40 FS
38	1		*LH REAR SPOILER	Necessary	682.40 FS	*682.40 FS
39	4		*CLIP SHARKFIN RH/LH LEVANTE	Necessary	30.40 FS	*30.40 FS
40	1		*LUGGAGE COMPARTMENT SEAL	Not Necessary	565.60 FS	*- FS
41	1		*REAR WINDOW GLASS	Necessary	4,282.40 FS	*4,282.40 FS
42	2		*WINDSHIELD SUPPORT PIN	Necessary	30.00 FS	*30.00 FS
43	1		*PROTECTIVE FILM	Necessary	129.90 FS	*129.90 FS
44	8		*FASTENER CLIP	Necessary	39.60 F	*39.60 F

F=Franchise part. S=SpcNett.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Total Parts (S\$)	25,645.35	17,832.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE DAMAGED BODY PARTS AND REPLACE EFFECTE	New	10,560.00	3,960.00
2	LABOUR TO TRANSFER BOOTLID MECHANISM	New	2,640.00	660.00
3	LABOUR TO REMOVE & INSTALL LUGGAGE COMPARTMEN	New	2,640.00	0.00
4	LABOUR TO REPLACE REAR WINDSCREEN	New	1,320.00	1,320.00
5	TO SPRAY PAINT ON REAR OUTER PANEL & INNER PANEL	New	6,500.00	3,250.00
6	TO CHECK AND CLEAR FAULT AFTER ACCIDENT REPAIR	New	1,200.00	1,200.00
7	TO CHECK ELECTRICAL WIRING SYSTEMFOR PROPER FU	New	660.00	330.00
8	LABOUR TO REPAIR END PANEL	New	1,320.00	0.00
9	LABOUR TO REMOVE & INSTALL LUGGAGE COMPARTMENT	New	660.00	660.00
10	SPRAY PAINT END PANEL	New	650.00	0.00
			Gross Labour Cost (\$\$)	28,150.00
				11,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >