

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21010857/DTY3Q2
Date: 16/03/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	SNM21D206011
Claimant Vehicle No :	SJK8533A	Insured Vehicle No :	GBJ4689K
Date of Loss:	21/10/2021	Nature of Claim:	TP
		Claim No:	SNM21D206011/C02/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJK8533A	Engine No:	1NZC997316
Make & Model:	TOYOTA AXIO, 1.5 (A)	Chassis No:	NZE1416076637
Reg. Date:	08/11/2008 (Man. Year: 2008)	Odometer:	129087 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/45 R16	Rear Tyre Size:	205/45 R16
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,085.12	3,311.47	11,773.65	78.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,020.00	1,910.00	4,110.00	68.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,105.12	5,221.47	15,883.65	75.26
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	21,105.12	4,000.00	17,105.12	81.05
+ GST 7.00/7.00% (S\$)	1,477.36	280.00	1,197.36	81.05
Nett Amount (S\$)	22,582.48	4,280.00	18,302.48	81.05

INSPECTION

Date of Assignment:	18/11/2021	
Date Inspected:	22/10/2021	Inspected At:
		JWG International Pte Ltd (HQ) Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint Singapore 568047
Estimated Period of Repair:	5.0 days	

3/16/22, 9:02 AM

Adjuster Report

Adjuster: BRYAN TANI

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Mar 2022)
Parts:	143	TOYOTA AXIO 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJK8533A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	1,096.90 FL	*849.30 FL
2	1		*BOOTLID LOCK	Damaged	155.10 FL	*155.10 FL
3	1		*BOOTLID CENTER GARNISH	Cracked	297.60 FL	*297.60 FL
4	1		*BOOTLID LOGO	Necessary	71.70 FL	*68.50 FL
5	2		*BOOTLID HINGE L+R	Repair	322.80 FL	*- FL
6	1		*BOOTLID INNER TRIM	Serviceable	419.20 FL	*- FL
7	1		*BOOTLID WEATHER STRIP	Deformed	309.60 FL	*211.50 FL
8	2		*BOOTLID NO PLATE LAMP L+R	Not Necessary	104.20 FL	*- FL
9	1		*BOOTLID CYLINDER LOCK	Not Necessary	149.00 FL	*- FL
10	1		*REAR BUMPER	Dented	869.20 FL	*483.00 FL
11	2		*REAR BUMPER SIDE RETAINER L+R	Serviceable	171.60 FL	*- FL
12	2		*REAR BUMPER BRACKET L+R	Serviceable	169.40 FL	*- FL
13	2		*REAR FENDER L+R	Not Necessary	3,299.20 FL	*- FL
14	1		*REAR FENDER INNER TRIM L+R	O/S Deformed /N/S NotNecessary	1,527.00 FL	*378.46 FL
15	2		*REAR FENDER AIR DUCT L+R	Not Necessary	198.00 FL	*- FL
16	2		*REAR END PANEL	Dented	1,190.80 FL	*568.20 FL
17	2		*REAR END PANEL TOP GARNISH	Mtg Cracked	329.40 FL	*275.30 FL
18	1		*SPARE WHEEL PANEL	Repair	1,407.20 FL	*- FL
19	1		*SPARE WHEEL PANEL TOP BOARD	Serviceable	618.70 FL	*- FL
20	2		*SPARE WHEEL PANEL TOOL BOX	Not Necessary	510.00 FL	*- FL
21	2		*TAIL LAMP L+R	Cracked	1,593.40 FL	*735.00 FL
22	2		*TAIL LAMP PANEL L+R	Repair	898.80 FL	*- FL
23	2		*TAIL LAMP LOWER BRACKET L+R	Serviceable	163.60 FL	*- FL
24	1		*EXHAUST PIPE	Repair	1,492.80 FL	*- FL
25	1		*EXHAUST HEAT SHIELD	Not Necessary	210.40 FL	*- FL
26	1		*EXHAUST MOUNTING	Not Necessary	87.50 FL	*- FL
27	1		*REAR WINDSCREEN MOULDING	Not Necessary	210.40 FL	*- FL
28	1		*REAR NUMBER PLATE	Serviceable	90.00 FS	*- FS
29	1		*SET REAR REVERSE SENSOR	Damaged	300.00 FS	*220.00 FS
30	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
31	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	80.00 FS	*- FS
32	1		*FENDER SEALANT	Not Necessary	80.00 FS	*- FS
33	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
34	1		*TAIL PANEL SEALANT	Not Necessary	120.00 FS	*- FS
35	1		*REVERSE CAMERA	Not Necessary	600.00 FS	*- FS
36	1		*REAR BOOTLID INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
37	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
38	1		*REAR FENDER INNER TRIM CLIPS	Serviceable	50.00 FS	*- FS
39	1		*TAIL LAMP CLIPS	Not Necessary	50.00 FS	*- FS
40	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 19,553.50 4,316.96

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 25.00/25.00% (S\$)					4,468.38	1,005.49
Total Parts (S\$)					15,085.12	3,311.47

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	300.00	80.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	800.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	800.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO RNR REVERSE CAMERA	New	100.00	0.00
6	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	New	250.00	0.00
7	TO RNR REAR BOOT MECHANISM TO FACILITATE REPAIRS	New	200.00	60.00
8	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	New	250.00	60.00
9	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
10	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
11	TO RNR REVERSE SENSOR TO ASSIST WORK LOAD	New	120.00	40.00
Gross Labour Cost (\$\$)			6,020.00	1,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >