

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21010860/ETCN2**Date:** 24/04/2022**REFERENCE**

Insured/Claimant: GHARIWALA AJAYKUMAR JASHVANTLAL
Date of Loss: 20/10/2021

Policy No: 1800080689
Nature of Claim: OD Claim No: 4231448341SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMC6242J**
Make & Model: AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A) Engine No: CVK061956
Reg. Date: 12/07/2018 (Man. Year: 2018) Chassis No: WAUZZZF56JA101878
Colour: Black Odometer: 0 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$135,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/35ZR19 Rear Tyre Size: 255/35ZR19
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm
Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	43,794.00	27,038.32	16,755.68	38.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	17,274.00	10,724.00	6,550.00	37.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	61,068.00	37,762.32	23,305.68	38.16
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	60,268.00	36,962.32	23,305.68	38.67
+ GST 7.00/7.00% (S\$)	4,218.76	2,587.36	1,631.40	38.67
Nett Amount (S\$)	64,486.76	39,549.68	24,937.08	38.67

INSPECTION

Date of Assignment: 22/10/2021

Date Inspected: 22/10/2021 Inspected At:

24 BENOI SECTOR
SINGAPORE 629857
REPAIRER: PREMIUM AUTOMOBILES PTE LTD

Estimated Period of Repair: 17.0 days

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	2,941.00 FS	*2,352.80 FS
2	1		*FRONT BUMPER GRILLE	Not Necessary	511.00 FS	*- FS
3	1		*FRONT BUMPER AIR GUIDE GRILLE-RH	Not Necessary	519.00 FS	*- FS
4	1		*FRONT BUMPER AIR GUIDE TRIM-RH	Not Necessary	48.00 FS	*- FS
5	1		*FRONT BUMPER SENSOR SUPPORT-RH	Not Necessary	51.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE-RH	Not Necessary	63.00 FS	*- FS
7	1		*FRONT RADIATOR GRILLE	Broken	1,493.00 FS	*1,194.40 FS
8	1		*FRONT BUMPER SECURING STRIP	Broken (1 Pc only)	71.00 FS	*28.16 FS
			2 Pcs			
9	1		*FRONT BUMPER GUIDE SECTION-RH	Broken	36.00 FS	*28.72 FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Broken	124.00 FS	*99.20 FS
11	1		*FRONT BUMPER CARRIER	Broken	845.00 FS	*675.60 FS
12	1		*FRONT BUMPER BRACKET-RH	Bent	214.00 FS	*171.20 FS
13	1		*FRONT BUMPER TOP COVER	Broken	127.00 FS	*101.60 FS
14	1		*CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
15	1		*AIR-CONDITIONER STICKER	Necessary	8.00 FS	*5.68 FS
16	1		*FRONT BUMPER LOCK CARRIER BRACKET	Broken	137.00 FS	*109.60 FS
17	2		*FRONT BUMPER SUPPORT-LH/RH	Necessary	58.00 FS	*44.96 FS
18	2		*FRONT PARKING AID SENSOR-INNER/OUTER	Not Necessary	0.00 FS	*- FS
19	1		*FRONT PARKING AID SENSOR SEAL	Necessary	9.00 FS	*7.04 FS
			4 Pcs			
20	1		*HORN-RH	Not Necessary	126.00 FS	*- FS
21	1		*HORN BRACKET-RH	Not Necessary	29.00 FS	*- FS
22	1		*FRONT FENDER-RH	Dented	1,060.00 FS	*848.00 FS
23	1		*FRONT FENDER ATTACHMENT PART	Not Necessary	53.00 FS	*- FS
24	1		*FRONT FENDER CLOSING ELEMENT-RH	Necessary	74.00 FS	*59.04 FS
25	1		*FRONT FENDER BRACKET-RH	Necessary	35.00 FS	*27.92 FS
26	1		*FRONT FENDER BRACE-RH	Bent	118.00 FS	*94.40 FS
27	1		*FRONT FENDER CENTER BRACKET-RH	Not Necessary	49.00 FS	*- FS
28	1		*FRONT FENDER CHROME TRIM-RH	Necessary	164.00 FS	*130.80 FS
29	1		*FRONT WHEEL HOUSING LINER-RH	Not Necessary	275.00 FS	*- FS
30	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	169.00 FS	*- FS
31	1		*FRONT WHEEL SPOILER	Not Necessary	73.00 FS	*- FS
32	1		*FRONT BUMPER SPOILER-RH	Not Necessary	36.00 FS	*- FS
33	1		*FRONT FENDER LEDGE COVER	Necessary	36.00 FS	*28.24 FS
34	1		*FRONT FENDER COVER-RH	Necessary	16.00 FS	*12.24 FS
35	1		*FRONT BONNET	Dented	3,312.00 FS	*2,649.60 FS
36	1		*FRONT BONNET RETAINING CLIP	Necessary	4.00 FS	*2.64 FS
			3 Pcs			
37	6		*CAP NUT	Necessary	24.00 FS	*19.20 FS
38	1		*FRONT BONNET ATTACHMENT PART	Not Necessary	123.00 FS	*- FS
39	2		*FRONT BONNET HINGE-LH/RH	Not Necessary	838.00 FS	*- FS
40	1		*FRONT BONNET IMPACT PROTECTION-CENTER/LH/RH	Necessary	84.00 FS	*65.68 FS
			3 Pcs			
41	1		*FRONT BONNET INSULATION PAD	Crushed	343.00 FS	*274.40 FS
42	1		*FRONT BONNET STRICKER-RH	Bent	50.00 FS	*39.92 FS
43	1		*FRONT BONNET LOCK	Bent	214.00 FS	*170.80 FS
44	2		*FRONT BOWDEN CABLE	Bent	116.00 FS	*92.00 FS
45	1		*FRONT BOWDEN CABLE COVER	Not Necessary	10.00 FS	*- FS
46	1		*FRONT BOWDEN RELEASE LEVER	Torn	14.00 FS	*10.48 FS
47	1		*HEADLIGHT-RH	Broken	7,902.00 FS	*6,321.60 FS
48	1		*HEADLIGHT POWER MODULE	Not Necessary	758.00 FS	*- FS
49	1		*HEADLIGHT CONTROL UNIT	Not Necessary	751.00 FS	*- FS
50	1		*HEADLIGHT HEAT SINK-RH	Broken	1,153.00 FS	*922.40 FS
51	1		*HEADLIGHT LIFT CYLINDER-RH	Broken	198.00 FS	*158.40 FS
52	1		*HEADLIGHT LIFT CYLINDER BRACKET-RH	Broken	15.00 FS	*11.76 FS
53	1		*HEADLIGHT CORRUGATED PIPE	Not Necessary	86.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*FRONT RADIATOR LOCK CARRIER	Broken	1,016.00 FS	*812.80 FS
55	1		*FRONT RADIATOR CORE SUPPORT	Broken	38.00 FS	*30.32 FS
56	1		*FRONT TEMPERATURE SENSOR BRACKET	Necessary	19.00 FS	*14.56 FS
57	1		*AIR COOLER	Not Necessary	587.00 FS	*- FS
58	1		*AIR COOLER SEAL	Not Necessary	92.00 FS	*- FS
59	1		*AIR COOLERPRESSURE HOSE	Not Necessary	357.00 FS	*- FS
60	1		*AIR CON CONDENSER	Dented	622.00 FS	*497.60 FS
61	1		*FRONT RADIATOR	Dented	904.00 FS	*722.80 FS
62	1		*COOLANT	Necessary	142.00 FS	*113.28 FS
		6 Pcs				
63	1		*FAN RING	Broken	267.00 FS	*213.20 FS
64	1		*RADIATOR FAN WITH CONTROL UNIT	Not Necessary	2,318.00 FS	*- FS
65	1		*FRONT RADIATOR AIR GUIDE-INNER RH	Missing	31.00 FS	*24.64 FS
66	1		*FRONT RADIATOR AIR GUIDE-OUTER RH	Broken	16.00 FS	*12.80 FS
67	1		*FRONT RADIATOR AIR GUIDE-LOWER	Not Necessary	22.00 FS	*- FS
68	1		*INTAKE AIR DUCT-RH	Broken	22.00 FS	*17.20 FS
69	1		*ENGINE AIR GUIDE	Broken	53.00 FS	*42.40 FS
70	1		*AIR FILTER	Not Necessary	386.00 FS	*- FS
71	1		*AIR INTAKE HOSE	Not Necessary	95.00 FS	*- FS
72	1		*AIR MASS METER	Not Necessary	567.00 FS	*- FS
73	1		*NOISE INSULATION	Not Necessary	572.00 FS	*- FS
74	1		*FRONT DOOR CHROME TRIM-RH	Necessary	164.00 FS	*130.80 FS
75	1		*FRONT NO PLATE	Bent	100.00 FS	*80.00 FS
76	1		*SUNDRIES	Necessary	450.00 FS	*94.64 FS
77	1		*HEADLIGHT STICKER	Not Necessary	0.00 FS	*- FS
78	1		*FRONT BUMPER WIRING SET	Torn	510.00 FS	*408.00 FS
		Supplementary				
79	1		*BONNET STRIKER - LH	Bent	5.00 FS	*39.92 FS
		Supplementary				
80	1		*BONNET LOCK CBALE	Torn	74.00 FS	*58.64 FS
		Supplementary				
81	1		*FRONT REINFORCEMENT BEAM BRACKET - LH	Bent	214.00 FS	*171.20 FS
		Supplementary				
82	1		*RADIATOR AIR GUIDE - LH INNER	Broken	32.00 FS	*24.88 FS
		Supplementary				
83	1		*RADIATOR AIR GUIDE - LH OUTER	Broken	16.00 FS	*12.80 FS
		Supplementary				
84	1		*RADIATOR AIR GUIDE - CENTER	Not Necessary	16.00 FS	*- FS
		Supplementary				
85	1		*RADIATOR SUPPORT - LH	Not Necessary	76.00 FS	*- FS
		Supplementary				
86	1		*LED HEADLIGHT - LH	Broken	7,902.00 FS	*6,321.60 FS
		Supplementary				
87	1		*BONNET LOCK - LH	Bent	214.00 FS	*170.80 FS
		Supplementary				
88	1		*HEADLIGHT COMPENSATING PIECE	Missing	80.00 FS	*63.68 FS
		Supplementary				
89	1		*RADIATTOR GRILLE INNER COVER	Broken	238.00 FS	*190.40 FS
		Supplementary				

F=Franchise part. S=SpcNett.

Total Parts (S\$) 43,794.00 27,038.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO RENEW AND RENEW AIRCON CONDENSER,CHARGED AIR COOLER AND RADIATOR.TO RENEW ADDITIONAL RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS	New	1,700.00	1,700.00
4	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM.TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR	New	280.00	280.00
5	TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER,BONNET AND RHS HEADLIGHT.TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.RE-ORGANOZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	5,600.00	3,000.00
6	TO RESPRAY FRONT BUMPER,RHS FRONT FENDER,BONNET,HINGES AND RHS FRONT DOOR	New	4,500.00	2,200.00
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
8	TO REPAIR BOTH UPPER A-PILLAR Supplementary	New	800.00	250.00
9	TO RESPRAY BOTH UPPER A-PILLAR AND LHS FRONT DOOR Supplementary	New	2,450.00	1,650.00
10	TO REMOVE AND REINSTALL LHS FRONT DOOR PILLAR TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR Supplementary	New	280.00	280.00
11	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE Supplementary	New	400.00	250.00
Gross Labour Cost (\$)			17,274.00	10,724.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >