

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21010862/TPA3Q2**Date:** 11/08/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100484396-05
<b>Claimant Vehicle No :</b>	FBQ4145B	<b>Insured Vehicle No :</b>	SDM693J
Date of Loss:	11/10/2021	Nature of Claim:	TP
		Claim No:	2163417046SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>FBQ4145B</b>	Engine No:	G3E6E0510078
Make & Model:	YAMAHA SNIPER T150, 150cc	Chassis No:	MH3UG0740K0153210
Reg. Date:	25/09/2019 (Man. Year: 2019)	Odometer:	0 km
Colour:	Red/Black		
Engine Capacity:	150 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	80/90 R17	Rear Tyre Size:	110/70 R17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,004.00	2,836.00	1,168.00	29.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,130.00	530.00	600.00	53.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,134.00</b>	<b>3,366.00</b>	<b>1,768.00</b>	<b>34.44</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,650.00</b>		
<b>(S\$)</b>	5,134.00	2,650.00	2,484.00	48.38
<b>+ GST 7.00/7.00% (S\$)</b>	359.38	185.50	173.88	48.38
<b>Nett Amount (S\$)</b>	<b>5,493.38</b>	<b>2,835.50</b>	<b>2,657.88</b>	<b>48.38</b>
<b>+ Loss of Use (4.0 x S\$30.00/day) (S\$)</b>		120.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,957.50</b>		
<b>Global Sum Settlement (S\$)</b>		<b>2,950.00</b>		

INSPECTION

Date of Assignment:	22/10/2021	
Date Inspected:	22/10/2021	Inspected At: Yew Tee Automobile Tech Pte Ltd (Woodlands) 39 Woodlands Close #01-12, Mega@Woodlands Singapore 737856
Estimated Period of Repair:	4.0 days	

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Missing	180.00 FL	*180.00 FL
2	1		*FRONT FORK LH (LOCAL REPAIR) }	Scratched	198.00 FS	*120.00 FS
3	1		*FRONT FORK RH }		198.00 FS	*- FS
4	1		*FRONT TOP FAIRING	Missing	340.00 FL	*340.00 FL
5	1		*FRONT LOWER INNER FAIRING	Distorted	370.00 FL	*370.00 FL
6	1		*FRONT LOWER LAMP LH	Cracked	130.00 FL	*130.00 FL
7	1		*FRONT LOWER LAMP RH	Cut	130.00 FL	*130.00 FL
8	1		*FRONT HEADLAMP	Cut	430.00 FL	*430.00 FL
9	1		*FRONT HEADLAMP TOP FAIRING	Not Necessary	120.00 FL	*- FL
10	1		*FRONT HEADLAMP LOWER FAIRING	Not Necessary	170.00 FL	*- FL
11	1		*FRONT HEADLAMP LOWER INNER FAIRING	Not Necessary	180.00 FL	*- FL
12	1		*FRONT SIDE FAIRING LH	Cracked	330.00 FL	*330.00 FL
13	1		*FRONT SIDE FAIRING RH	Cracked	330.00 FL	*330.00 FL
14	1		*FRONT SIDE FAIRING LAMP LH	Cut	210.00 FL	*210.00 FL
15	1		*FRONT SIDE FAIRING LAMP RH	Not Necessary	210.00 FL	*- FL
16	1		*REAR FAIRING LH	Cut	280.00 FL	*280.00 FL
17	1		*FRONT SIDE MIRROR LH	Cut	75.00 FL	*75.00 FL
18	1		*FRONT CENTRE LOWER INNER SHIELD	Deformed	135.00 FL	*135.00 FL
19	1		*REAR BOX	Not Necessary	280.00 FS	*- FS
20	1		*CENTRE INNER BASKET	Deformed	70.00 FS	*70.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,366.00	3,130.00
- List Item Discount on L Items 10.00/10.00% (S\$)	362.00	294.00
Total Parts (S\$)	4,004.00	2,836.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE AND REFIT FRONT UNDERCARRIAGE	New	220.00	60.00
2	TO DISCONNECT AND RECONNECT CHECK ELECTRICAL WIRING HARNESS WIRE ,SOCKETS ,REPLACE DAMAGED PARTS	New	30.00	30.00
3	TO CONDUCT COMPUTER WHEEL ALIGNMENT	New	80.00	40.00
4	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS ,STRAIGHTEN ,KNOCK OUT ,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS .TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	450.00	200.00
5	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS ,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER ,CLEANING AND SANDING OF SURFACES FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	350.00	200.00
<b>Gross Labour Cost (\$)</b>			<b>1,130.00</b>	<b>530.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >