

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 6736D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR WHEEL RIM LH	CUT	1,555.00	1,555.00
1	REAR FENDER LH	BUCKLED	836.70	836.70
	LESS 25% DISCOUNT		-597.93	-597.93
			1,793.77	1,793.77
<u>NETT ITEMS</u>				
1	REAR DOOR APPS LH (N)	NECESSARY	80.00	80.00
1	REAR FENDER (PETROL ONLY) LH (N)	NECESSARY	40.00	40.00
	LESS 10% DISCOUNT		-12.00	-12.00
			108.00	108.00
<u>SPECIAL NETT ITEMS</u>				
1	REAR DOOR APPS LH (SN)	REPEATED	80.00	-
1	REAR DOOR ADV STICKER LH (SN)	NECESSARY	100.00	100.00
1	REAR WESTLAKE TYRE LH (SN)	SERVICEABLE	216.00	-
			396.00	100.00
<u>LABOUR</u>				
	PANEL BEATING-REAR FENDER LH.		800.00	350.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
			1,520.00	850.00
GRAND TOTAL			3,817.77	2,851.77
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				2,300.00

Report Ref No. NS/INC21010867/Vqcn2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.