

Our Job Ref No : 305490585

Date : 14/10/2021

# ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508989  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK

Fax :

Attn : THEVAN

: SHA1780A

DOA: 13/10/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- FBC3930G

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

**Total for Part-By-Part Repair Cost**

+

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

**Final Lumpsum Repair cost**

\$1,050.00

3. Estimated normal period for repairs: 2 working days

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : JUMANI

Tel : 6214 8315

Fax : 65468156

Signature: 

Name : THEVAN

Date : 22/10/21

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	7.49 / 2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

\_\_\_\_\_

\_\_\_\_\_



*HTUC - (4 sum)*

COMFORTDELGRO ENGINEERING PTE LTD

Date: 14.10.2021

Time: 14:26:37

*Jumani*

REPAIR ESTIMATE

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305490585  
REGN NO : SHA1780A ✓  
MILEAGE : 000000000 ✓  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 11.01.2017  
DATE/TIME IN : 14.10.2021 11:30  
ACCIDENT DATE : 13.10.2021

JOB / PARTS DESCRIPTION QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	COVER ASSY-RR BUMPER#	1	553.00	20.00	442.40	✓/ent
0002	04-01-0103-0738-G	COVER-RR BUMPER LWR#	1	228.00	20.00	182.40	✓/scr
0003	04-01-0103-0740-G	BEAM-RR BUMPER#	1	428.40	20.00	342.72	✓ X SUC
0004	04-01-0103-0739-G	ABSORBER-RR BUMPER ENERGY	1	103.50	20.00	82.80	✓ X SUC
0005	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	20.00	20.00	16.00	✓/ncc

SUB-TOTAL : 1,066.32

JOB NATURE

0000	PB	PANEL BEATING		300.00		280	
0001	SP	SPRAYPAINT CHARGE		300.00		250	
0002	20-05	RENEW ADVERTISEMENT STICKER-Bumper				50.00	✓/ncc
0003	L	REMOVE/REFIX REVERSE SENSOR		80.00		30	

SUB-TOTAL : 730.00

*Thuvan @ Lkhqy to . com  
82235769  
14/10/21 / 1630  
2 days w/p  
L/S for after repair photo*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: