

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG21010873/VVF3E2

Date: 15/11/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800110064
Claimant Vehicle No : SBS8308L Insured Vehicle No : YP7584E
Date of Loss: 21/10/2021 Nature of Claim: TP Claim No: 8715571172SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBS8308L**
Make & Model: SCANIA KUB4X2, 8.9 ABS TURBO 2WD (A) Engine No: 6376538
Reg. Date: 18/08/2008 (Man. Year: 2008) Chassis No: YS2K4X20001861340
Colour: Multi-colour Odometer: 1218148 km
Engine Capacity: 8867 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D)
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5/5 mm
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	37.00	37.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	184.00	184.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	221.00	221.00	0.00	0.00
+ GST 7.00/7.00% (S\$)	15.47	15.47	0.00	0.00
Nett Amount (S\$)	236.47	236.47	0.00	0.00

INSPECTION

Date of Assignment: 22/10/2021
Date Inspected: 22/10/2021 Inspected At: Sbs Transit Ltd (Bedok) (HQ)
1470 BEDOK NORTH AVE 4
Singapore 489946
Estimated Period of Repair: 0.5 days

Adjuster: Thevan Thomas Karthikesavan

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MOUNTING BRKT;MALE;540N;MIRROR ARM. MA	Distorted	20.00 F	*20.00 F
2	1		*MOUNTING BRKT;FEMALE;540N;MIRROR ARM. MA	Distorted	17.00 F	*17.00 F
F=Franchise part.						
Total Parts (S\$)					37.00	37.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WORKSHOP LABOUR COST	New	184.00	184.00
Gross Labour Cost (\$\$)			184.00	184.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >