



Accident Reference & Bus No: **E/4520/2021 - SBS8308L with YP7584E**

Activated date: Fri 22/10/2021 14:33

Activated by: Yao Tianhao <yaoth@sbstransit.com.sg>

Estimate for

Stock Code	Description	Quantity	Total Material cost(S\$)
		0	\$0.00
30107529	MOUNTING BRKT;MALE;540N;MIRROR ARM. MA	1	\$20.00
30107530	MOUNTING BRKT;FEMALE;540N;MIRROR ARM. MA	1	\$17.00
(MO Number : BN2110002176)		Sub Total S\$:	37.00

DIS
DIS

- ☒ Parts cost: \$ 37
- ☐ Contractor Labour cost: \$ 0
- ☒ Workshop Labour cost: \$ 184
- ☐ Advertisement Cost: \$ 0
- ☒ Repair period: 0.5 day

- ☐ Tow Cost: \$ 0
- ☐ Loss of use: \$ LKK not required
- ☐ Overheads: \$ LKK not required

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: