

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/GRB21010874/KES3Q2  
**Date:** 15/12/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
<b>Claimant Vehicle No :</b>	GBH3527L	<b>Insured Vehicle No :</b>	SLJ2730T
Date of Loss:	13/10/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0004512

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBH3527L</b>		
Make & Model:	TOYOTA HIACE, 3.0 (A)	Engine No:	1KD2759169
Reg. Date:	11/05/2018 (Man. Year: 2017)	Chassis No:	KDH2010235707
Colour:	White	Odometer:	85105 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	OHTSU 7 mm	Rear Left Side:	OHTSU 6 mm
Front Right Side:	OHTSU 7 mm	Rear Right Side:	OHTSU 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,093.50	1,471.00	2,622.50	64.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	1,230.00	1,170.00	48.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,493.50</b>	<b>2,701.00</b>	<b>3,792.50</b>	<b>58.40</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,150.00</b>		

(S\$)	6,493.50	2,150.00	4,343.50	66.89
<b>+ GST 7.00/7.00% (S\$)</b>	454.55	150.50	304.05	66.89
<b>Nett Amount (S\$)</b>	<b>6,948.05</b>	<b>2,300.50</b>	<b>4,647.55</b>	<b>66.89</b>
<b>Global Sum Settlement (S\$)</b>	<b>0.00</b>			

INSPECTION

Date of Assignment: 22/10/2021

Date Inspected: 22/10/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Car Times Autolution Pte Ltd (HQ)  
 160 Sin Ming Drive #02-04, AutoCity  
 Singapore 575722

**Adjuster:** KENNETH KONG**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 14 Dec 2021)	
<b>Parts:</b>	N/A	TOYOTA HIACE 3.0 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBH3527L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent / Cracked	600.00 FL	*600.00 FL
2	1		*FRONT BUMPER RETAINER RHS	Cracked	150.00 FL	*150.00 FL
3	1		*FRONT FOG LAMP COVER RHS	Serviceable	70.00 FL	*- FL
4	1		*FRONT DOOR RHS	Repair	1,870.00 FL	*- FL
5	1		*FRONT HEADLAMP RHS	Cut	898.00 FL	*898.00 FL
6	1		*FRONT SIDE STEP COVER RHS	Dented / Cut	200.00 FL	*200.00 FL
7	1		*FRONT GRILLE BASE	Serviceable	530.00 FL	*- FL
8	1		*FRONT TOP GRILLE	Serviceable	200.00 FL	*- FL
9	1		*FRONT LOWER GRILLE	Serviceable	340.00 FL	*- FL
10	1		*BUMPER LOWER GRILLE	Serviceable	230.00 FL	*- FL
11	1		*FRONT FENDER LHS	Repair	250.00 FL	*- FL
12	1		*DOOR STICKER	Necessary	30.00 FS	*25.00 FS
13	1		*SET BUMPER CLIPS	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>5,428.00</b>	<b>1,933.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	1,334.50	462.00
<b>Total Parts (S\$)</b>	<b>4,093.50</b>	<b>1,471.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,REPLACE DAMAGED PARTS AND COMPONENTS	New	1,200.00	600.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	1,000.00	600.00
3	TO REMOVE AND REFIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS	New	100.00	30.00
4	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	New	100.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>2,400.00</b>	<b>1,230.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >