

Not Authorised
11 Pm @
Resurvey After Repair
3 days

VEHICLE NO: GBH3527L

MODEL: TOYOTA HIACE

CHASSIS NO: KDH2010235707

DESCRIPTION	REPAIRER'S ESTIMATE(S\$)
<u>PARTS (LIST ITEMS)</u>	
FRONT BUMPER	Plum \$ 600.00 ✓
FRONT BUMPER RETAINER RHS	cm \$ 150.00 ✓
FRONT FOG LAMP COVER RHS	\$ 70.00 X
FRONT DOOR RHS	R \$ 1,870.00 X
FRONT HEADLAMP RHS	cm \$ 898.00 ✓
FRONT SIDE STEP COVER RHS	Plum \$ 200.00 ✓
FRONT GRILLE BASE	SL \$ 530.00 X
FRONT TOP GRILLE	SL \$ 200.00 X
FRONT LOWER GRILLE	SL \$ 340.00 X
BUMPER LOWER GRILLE	SL \$ 230.00 X
FRONT FENDER LHS	R \$ 250.00 X
	\$ 5,338.00
	25% \$ 1,334.50
	\$ 4,003.50
<u>SPECIAL NETT ITEMS</u>	
DOOR STICKER	SL \$ 30.00 25%
BUMPER CLIPS I SET	SL \$ 60.00 ✓
Total	\$ 90.00
TOTAL PARTS	\$ 4,093.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ 1,200.00	600
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ 1,000.00	600
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ 100.00	30
4	To provide anti-rust treatment on affected areas	\$ <i>nn</i> 100.00	
	Labour Total :	\$ 2,400.00	
	TOTAL (PARTS & LABOUR):	\$ 6,493.50	