

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21010876/UQF3E2

Date: 18/11/2021

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001836315		
Claimant Vehicle No :	GBD8776Y	Insured Vehicle No :	SME5027K		
Date of Loss:	14/10/2021	Nature of Claim:	TP	Claim No:	264130

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD8776Y		
Make & Model:	MITSUBISHI CANTER, 3.0 D FEA01BR2SDEB (CBU) (M)	Engine No:	4P10B61216
Reg. Date:	26/06/2015 (Man. Year: 2015)	Chassis No:	FEA01BA10087
Colour:	White	Odometer:	169100 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15 (D)
Front Left Side:	Austone 6 mm	Rear Left Side:	Austone 6/6 mm
Front Right Side:	Austone 6 mm	Rear Right Side:	Austone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,344.20	2,088.57	5,255.63	71.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	1,450.00	200.00	12.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,994.20	3,538.57	5,455.63	60.66
Approved Total (Overridden) (\$\$)		2,800.00		
(\$\$)	8,994.20	2,800.00	6,194.20	68.87
+ GST 7.00/7.00% (\$\$)	629.59	196.00	433.59	68.87
Nett Amount (\$\$)	9,623.79	2,996.00	6,627.79	68.87

INSPECTION

Date of Assignment:	22/10/2021	
Date Inspected:	22/10/2021 Inspected At:	Liu's Brother Auto (HQ) No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Nov 2021)	
Parts:	N/A	mitsubishi canter 3.0 D FEA01BR2SDEB (CBU) (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD8776Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	1,133.20 F	*780.90 FL
2	1		*FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
3	1		*FRONT GRILLE	Repair	426.80 F	*- FL
4	1		*FRONT PANEL	Repair	864.30 F	*- FL
5	1		*FRONT PANEL FUSO EMBLEM	Serviceable	149.00 F	*- FL
6	1		*FRONT LH DOOR	Repair	1,910.50 F	*- FL
7	1		*FRONT LH DOOR ROC STICKER	Necessary	48.00 FS	*35.00 FS
8	1		*FRONT LH STEP GARNISH	Cracked	613.20 F	*341.21 FL
9	1		*FRONT LH BUMPER PAD	Missing	488.50 F	*319.82 FL
10	1		*FRONT LH CORNER PANEL GARNISH	Cracked	486.90 F	*408.25 FL
11	1		*FRONT LH SIGNAL LAMP	Broken	313.60 F	*208.21 FL
12	1		*FRONT LH SIDE LAMP	Broken	187.50 F	*187.50 FL
13	1		*FRONT LH HEAD LAMP	Cracked	672.70 F	*492.21 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,344.20	2,773.10
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	684.53
Total Parts (\$\$)	7,344.20	2,088.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	50.00	20.00
2	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	60.00	0.00
3	TO REMOVE, REPLACE AND TRANSFER DOOR PANEL, FITTING AND MECHANISMS	New	60.00	0.00
4	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS	New	600.00	580.00
5	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP ON ACCIDENT AFFECTED	New	880.00	850.00
Gross Labour Cost (\$\$)			1,650.00	1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >