

# CHARTERED AUTO ASSESSORS

17 Joo Seng Road #08-129 Joo Seng Heights Singapore 360017 Reg No. 26910200X  
Tel: +65 9631 7008 Fax: +65 6281 9989 Email: charteredauto@gmail.com

Hamidah Binte Abdul Karim  
Block 140 Bedok Reservoir Road #04-1503  
Singapore 470140

Your Ref : SLM 516 T  
Our Ref : 2105024/CA  
Date : 23 June, 2021  
Survey : Third Party

## SURVEY REPORT

### PARTICULARS OF VEHICLE

Vehicle No.	: SLM 516 T	Propellant	: Petrol, Auto
Make	: Honda	Capacity	: 1500 cc
Type of Body	: 5 Doors Stationwagon	Mileage	: 132159
Year & Model	: 2017, Shutter 1.5G	Engine No	: L15B3537887
Colour	: Silver	Chassis No	: GK8-1006718
Passenger-cap	: 4	Road Tax	: March, 2022

### TYRES CONDITIONS

Front Left	: Yokohma	Worn	: 30%	Size	: 195/60 R15
Front Right	: Yokohma	Worn	: 30%	Size	: 195/60 R15
Rear Left	: Yokohma	Worn	: 30%	Size	: 195/60 R15
Rear Right	: Yokohma	Worn	: 30%	Size	: 195/60 R15

### PRE-ACCIDENT CONDITION (Static Test Only)

Handbrake	: Serviceable	Steering	: Serviceable
Footbrake	: Serviceable	Paintwork	: Good

### QUANTUM

Repair Estimate : \$ 16,331.80  
Revised Amount : \$ 11,600.00 (Lump-sum Without Prejudice)

Under normal circumstances, the repair period would be: eight ( 8 ) days.  
We have not authorised repairs.

Survey Done At : Precise Auto Service  
1 Kaki Bukit Avenue 6, #02-34/36  
Autobay @ Kaki Bukit  
Singapore, 417883

Assignment Date : 20 May, 2021  
Survey Date : 20 May, 2021  
Accident Date : 13 May, 2021  
Assignment Given By : Hamidah Binte Abdul Karim

Our Ref: 2105024/CA

Vehicle No. SLM 516 T

Description	Qty	Repair Estimate	Revised Amount	Remarks
Rear trunklid	1	1,193.20	1,193.20	Badly Bent
Rear trunklid hinge o/s & n/s	2	81.00	81.00	Distorted
Rear trunklid rubber stopper	2	17.00	17.00	To replace
Rear trunklid upper lock	1	256.40	256.40	Bent
Rear trunklid lower lock striker	1	34.70	34.70	Bent
Rear trunklid lock buzzer	1	80.10	80.10	Damaged
Rear trunklid weatherstrip	1	168.20	168.20	Torn/Deformed
Rear trunklid damper o/s & n/s	2	360.80	360.80	Bent/Stiffed
Rear trunklid outer chrome garnish	1	463.80	463.80	Holder Broken
Rear trunklid outer chrome garnish clip	8	28.00	28.00	To replace
Rear trunklid reverse camera	1	658.90	658.90	Harness Damaged
Rear trunklid H emblem	1	46.50	46.50	To replace
Rear trunklid SHUTTER emblem	1	55.40	55.40	To replace
Rear trunklid inner trimboard	1	390.40	390.40	Torn/Deformed
Rear trunklid inner trimboard clip	8	28.00	28.00	To replace
Rear trunklid keyless sensor	1	285.40	285.40	Damaged
Rear trunklid inner holding handle	1	65.90	65.90	Damaged
Rear windscreen glass moulding	1	149.20	149.20	To replace
Rear windscreen glass clip	14	77.00	77.00	To replace
Rear bumper fascia	1	1,150.40	1,150.40	Torn/Deformed
Rear bumper side retainer o/s & n/s	2	53.00	53.00	To replace
Rear bumper side attachment o/s & n/s	2	82.80	82.80	To replace
Rear bumper bracket o/s & n/s	2	77.40	77.40	Bent
Rear bumper reflector o/s & n/s	2	90.40	90.40	Holder Damaged
Rear bumper reflector garnish o/s & n/s	2	92.20	92.20	Grazed/Damaged
Rear bumper tow hook cover	1	46.50	46.50	Torn/Deformed
Rear bumper sponge o/s & n/s	2	112.00	112.00	To replace
Rear bumper clip	10	35.00	35.00	To replace
Rear end panel	1	560.20	560.20	Badly Bent
Rear end panel top trim	1	155.40	155.40	Torn/Deformed
Rear end panel top trim clip	4	14.00	14.00	To replace
Rear number plate lamp	2	77.00	77.00	Holder Damaged
Rear trunk panel cover board	1	655.20	655.20	Wrapped
Rear trunk panel lower insulation cloth	1	291.60	291.60	To replace
Rear trunk panel upper tool tray	1	345.20	345.20	Bent/Deformed
Rear trunk panel tool tray front cover	1	650.40	650.40	Torn/Deformed
Rear trunk panel lower sponge tool tray	1	312.80	312.80	Torn/Deformed
Rear fender inner trimboard o/s & n/s	2	966.40	966.40	Torn/Deformed
Rear fender inner trimboard clip o/s & n/s	20	110.00	110.00	To replace

-----  
10,317.80

-----  
10,317.80

-

2,063.56 Less 20%

Page Total :

-----  
10,317.80

-----  
8,254.24

Our Ref: 2105024/CA

Vehicle No. SLM 516 T

Description	Qty	Repair Estimate	Revised Amount	Remarks
Balance brought forward		10,317.80	8,254.24	
<b><u>SPECIAL NETT</u></b>				
Rear number plate	1	45.00	45.00	Damaged
Rear number plate Casing	1	29.00	29.00	Damaged
Rear windscreen inner seal	1	50.00	50.00	To replace
Rear windscreen sealant	1	60.00	60.00	To replace
Rear reverse sensor c/w control box	1 set	380.00	380.00	Damaged

Total Materials Cost :	10,881.80	8,818.24
------------------------	-----------	----------

**Labour & Miscellaneous Charges**

To provide towing service.	120.00	110.00
To remove/refit wire harness, all related connectors. Check proper function.	150.00	120.00
To check airbag assembly, sensors and control units. Reset to factory specifications.	280.00	250.00
To apply underseal and rust-proofing on the affected areas.	250.00	220.00
To set vehicle on chassis alignment bench, inclusive of all necessary preparatory works.	380.00	320.00
To remove/refit rear windscreen glass.	200.00	180.00

Page Total:	12,261.80	10,018.24
-------------	-----------	-----------

Our Ref: 2105024/CA

Vehicle No. SLM 516 T

Description	Qty	Repair Estimate	Revised Amount	Remarks
Balance brought forward		12,261.80	10,018.24	
<u>Labour &amp; Miscellaneous Charges</u>				
To install reverse sensors, control unit. Re-connect wires harness. Check function.		180.00	150.00	
To transfer rear trunklid mechanisms with motor assembly and all attachments.		150.00	120.00	
To remove/refit boot garnishes, speakers, interior garnishes, carpets where necessary.		180.00	150.00	
To straighten/align rear exhaust assembly with all attachments, brackets and holders.		280.00	250.00	
To position and install rear reverse camera. Re-connect wires harness. Check function.		180.00	150.00	
To putty and spray paint rear bumper, rear trunklid, rear trunklid outer garnish, rear end panel, rear trunk panel, o/s rear fender, n/s rear fender and repaired body parts inclusive of preparatory works and painting materials.		1,500.00	1,400.00	
To remove all damaged parts with all necessary components and attachments. To apply hot-works where necessary. Straighten/align chassis members, repair/reshape/align dented body panels, in accordance with factory specifications. Replace damaged parts, refit and align into position. Refit all necessary components/attachments.		1,600.00	1,500.00	
<b>Grand Total:</b>		<b>16,331.80</b>	<b>13,738.24</b>	

**Summary**

Total Material	10,881.80	8,818.24
Total Labour/Painting	5,450.00	4,920.00
Grand Total	16,331.80	13,738.24
<b>Lump-sum Amount</b>		<b><u>11,600.00</u></b>

Our Ref: 2105024/CA

Vehicle No. SLM 516 T

### CAUSE OF DAMAGE

The vehicle sustained impact to the rear.

### REMARKS

Having checked the scope of repair works we were satisfied that it was in accordance with the damage sustained. We also checked each item and have indicated its nature of damage. It was our opinion that these items were found damaged beyond repair and require replacement.

We checked the damage carefully and were of the opinion that the vehicle could be repaired.

We would therefore recommend repairs to be carried out at: \$ 11,600.00 on a lump-sum basis.

The survey was conducted on a without prejudice basis and we submit this report for your consideration.

CHARTERED AUTO ASSESSORS

Tan Chin Suan (Licensed Appraiser)

APRAISER, 1 Eng (C&A) 01102 (01102)