

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG21010880/GUF3E2

**Date:** 05/11/2021

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993661
<b>Claimant Vehicle No :</b>	SLR6191E	<b>Insured Vehicle No :</b>	SMT8375G
Date of Loss:	20/10/2021	Nature of Claim:	TP
		Claim No:	3140806526SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR6191E	Engine No:	P520462202
Make & Model:	MAZDA 3, 1.5 SEDAN AT EU6 (A)	Chassis No:	JM6BN22A8H0171706
Reg. Date:	22/08/2017 (Man. Year: 2017)	Odometer:	73744 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/45Z R18	Rear Tyre Size:	225/45Z R18
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	22/10/2021		
Date Inspected:	25/10/2021	Inspected At:	Wah Yu Automotive Body Work (HQ) 176 SIN MING DRIVE #05-09 Singapore 575721
Estimated Period of Repair:	6.0 days		

**Adjuster:** XING GUO QIANG

**Manager:** Tan Hui Zhen

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE: \$57,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	2		*REAR BUMPER TOW COVER	Missing	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	1		*REAR BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
5	1		*REAR BUMPER REINFORCEMENT	Dented	0.00 F	*- F
6	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
7	1		*REAR END PANEL	Repair	0.00 F	*- F
8	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
9	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
10	1		*BOOTLID	Buckled	0.00 F	*- F
11	3		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
12	1		*BOOTLID LOCK	Bent	0.00 F	*- F
13	1		*FRT NUMBER PLATE	Cut	0.00 F	*- F
14	1		*FRT NUMBER PLATE BASE	Cracked	0.00 F	*- F
15	1		*FRT BUMPER	Dented	0.00 F	*- F
16	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
17	1		*FRT BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
18	1		*FRT BUMPER REINFORCEMENT	Dented	0.00 F	*- F
19	1		*FRT BUMPER PAD	Cracked	0.00 F	*- F
20	1		*FRT BUMPER GRILLE	Cracked	0.00 F	*- F
21	1		*FRT GRILLE	Cracked	0.00 F	*- F
22	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
23	1		*FRT GRILLE CHROME MOULDING	Cracked	0.00 F	*- F
24	1		*FRT APRON PANEL	Deformed	0.00 F	*- F
25	1		*HORN	Cut	0.00 F	*- F
26	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
-------------------	------	------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >