

AJAX

Inspection Services Pte Ltd

Date : 13 July 2021

To : **918 Motoring Pte Ltd**
3 Ang Mo Kio Street 62
#01-07 Link @ Ang Mo Kio
Singapore 569139

AJAX Inspection Services Pte Ltd
120 Lower Delta Road
#08-08, Cendex Centre
Singapore 169208
Tel: +65 6255 0808
Fax: +65 6849 9155
info@ajaxinspection.com

Invoice No – AV29295
Company Reg No -201318067R
GST Reg No - 201318067R

TAX INVOICE

YOUR REF / CLAIM NUMBER : SKG1543B
OUR REF : AVS2021-27527/ID
TP VEHICLE NO : SKG1543B
CLAIM TYPE : INSPECTION REPORT
DATE OF SURVEY : 01 June 2021

No.	Description	Amount (\$\$)
1	Professional fee	600.00
Subtotal		600.00
GST 7.00%		42.00
Total		642.00

Payment Terms: 30 days from date of invoice

Please remit by electronic transfer as follows:
Payee: AJAX Inspection Services Pte Ltd
United Overseas Bank Ltd
Account No: 450-309-276-4
Email remittance advice to: accounts@ajaxadjusters.com

AJAX

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

INSPECTION REPORT

918 Motoring Pte Ltd
3 Ang Mo Kio Street 62 Link @ Ang Mo Kio St 62 #01-07 Singapore 569139

Assign Date:	01/06/2021	Inspection Date:	01/06/2021	TP Report Date:	31/05/2021
Accident Date:	29/05/2021	TP Policy No:	5118637474	Our Ref:	AVS2021-27527/ID
Place of Inspection:	918 Motoring Pte Ltd 3 Ang Mo Kio Street 62 Link @ Ang Mo Kio St 62 #01-07 Singapore 569139			Claimant:	Rosli Bin Abu Mansor

Description of Vehicle:

Veh. No:	SKG1543B	Make/Model:	Toyota Wish 1.8A
Colour:	Grey	Engine No:	1ZZ2488034
Engine Capacity:	1,794 cc	Chassis No:	ZNE100289762
Odometer:	343947	Reg. Date:	26/03/2006


Condition of Vehicle:

General:	Fair	Modification:	No	Steering:	Serviceable
Air-Conditioner:	Yes	Radio/Cassette/CD:	Yes	Wing Mirror:	Yes
Handbrake:	Serviceable	Footbrake:	Serviceable	Paint work:	Fair
Tyre Make:	Yokohama				
Front Tyre Size:	195/65R15	Front Left Side:	5mm	Front Right Side:	5mm
Rear Tyre Size:	195/65R15	Rear Left Side:	5mm	Rear Right Side:	5mm

Description of Damage:

The damage was found on the rear portion.

Point of Impact:



Adjuster:

Idram
Motor Appraiser

Date

COMPLETED 13 JUL 2021

Note: This report is confidential and solely for the use of the client. The inspection was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Adjustment of Repair Cost for Vehicle:

SKG1543B

Our Ref: AVS2021-27527/ID

No.	Qty	Description of Parts	Condition	Repairer's Estimate S\$	Our Recommendation S\$
List Items					
1	1	Rear windscreen	Cracked	1,403.20	1,403.20
2	1	Tailgate windscreen rubber moulding	Necessary	255.30	255.30
3	2	Windscreen heat strip LH/RH	Damaged	149.20	149.20
4	1	Wiper motor	Damaged	685.00	685.00
5	1	Wiper arm	Cracked	166.80	166.80
6	1	Rear tailgate	Deformed	1,485.00	1,485.00
7	1	Rear tailgate lock	Grazed	330.00	330.00
8	1	Rear tailgate lock catch	Re-use	94.20	--
9	1	Rear tailgate centre chrome moulding	Cracked	385.20	385.20
10	1	Rear tailgate garnish logo	Necessary	54.90	54.90
11	1	Rear tailgate number plate lamp	Re-use	173.00	--
12	1	Rear tailgate weatherstrip	Necessary	343.20	343.20
13	1	Rear tailgate inner board	Cut	680.00	680.00
14	2	Rear tailgate top trim LH/RH	Deformed	511.20	255.60
15	1	Rear tailgate top trim	Buckled	281.30	281.30
16	1	Rear fender trimboard LH	Cracked	761.00	761.00
17	1	Rear fender trimboard inner cover LH	Damaged	198.60	198.60
18	1	Rear fender centre trimboard LH	Damaged	455.20	455.20
19	1	Rear fender top trimboard LH	Damaged	298.30	298.30
20	1	Rear taillamp LH	Grazed	584.70	584.70
21	1	Rear bumper	Deformed	959.70	959.70
22	1	Rear bumper side retainer LH/RH	Damaged	230.40	115.20
23	1	Rear bumper reflector LH	Re-use	57.90	--
24	1	Rear end panel inner	Damaged	280.70	280.70
25	1	Rear end panel outer	Damaged	463.60	463.60
26	1	Rear end panel garnish	Damaged	245.50	245.50
27	1	Rear compartment panel cover board	Cut	599.70	599.70
28	1	Rear compartment panel cover board LH	Cut	380.00	380.00
29	1	Rear bumper bracket	Bent	84.20	84.20
30	1	Tailgate spoiler	Deformed	485.00	485.00

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Adjustment of Repair Cost for Vehicle:				SKG1543B	Our Ref: AVS2021-27527/ID
No.	Qty	Description of Parts	Condition	Repairer's Estimate S\$	Our Recommendation S\$
31	1	Tailgate 3rd brake light	Grazed	288.30	288.30
32	1	Taillamp panel LH	Repair	282.50	--
Sub Total:				13,652.80	12,674.40
Discount (less 25%):				3,413.20	3,168.60
				10,239.60	9,505.80

Special Nett Items					
1	1	Rear bumper reverse sensor	Malfunction	300.00	200.00
2	1	Rear reverse camera	Re-use	400.00	--
3	1	Rear wiper blade	Necessary	60.00	40.00
4	1	Tailgate chrome garnish clips	Necessary	50.00	30.00
5	1	Tailgate inner trim board clips	Necessary	50.00	30.00
6	1	Tailgate top inner garnish LH/RH clips	Necessary	50.00	30.00
7	1	Tailgate centre top garnish clips	Necessary	50.00	30.00
8	1	Rear fender trimboard LH clips	Necessary	100.00	40.00
9	1	Rear fender top trimboard LH clips	Necessary	100.00	40.00
10	1	Rear fender centre trimboard LH clips	Necessary	100.00	40.00
11	1	Windscreen sealant	Necessary	100.00	80.00
12	1	End panel sealant	Necessary	100.00	80.00
13	1	Tail lamp panel sealant	Not necessary	100.00	--
14	1	Rear no. plate & holder	Damaged	80.00	60.00
Sub Total:				1,640.00	700.00
Total Parts Price:				11,879.60	10,205.80

Labour Cost			
1	To remove & panel beat all damaged above parts & panels.	1,400.00	1,200.00
2	To respray new paintwork all damaged areas.	1,800.00	1,200.00
3	To remove all interior upholstery items to facilitate repairs.	300.00	200.00
4	To RNR rear windscreen to facilitate repairs.	200.00	150.00

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Adjustment of Repair Cost for Vehicle:				SKG1543B	Our Ref: AVS2021-27527/ID
No.	Qty	Description of Parts	Condition	Repairer's Estimate S\$	Our Recommendation S\$
5		To RNR reverse sensor to facilitate repairs.		80.00	60.00
6		To check & re-fix all electrical wirings.		60.00	50.00
7		To apply anti rust coating on all affected areas.		100.00	80.00
8		To check water leak test.		60.00	40.00
9		To do diagnosis and reset, reprogram or coding fault code.		400.00	280.00
10		To vacuum the interior.		100.00	60.00
Sub Total:				4,500.00	3,320.00
Grand Total:				16,379.60	13,525.80

Recommendation and Conclusion:

We have inspected the actual damages found on the vehicle and recommended the replacement of parts and repairs accordingly. The estimate repair cost is S\$16,379.60 . The repairer has agreed to undertake the repairs at our adjusted lumpsum amount of S\$ 9,600.00.

We have not authorised the repair. Under normal circumstances, estimated eight (8) working days are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.

The inspection was conducted entirely on a "Without Prejudice" basis.

AJAX

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Our Ref: AVS2021-27527/ID
Your Ref: SKG1543B




Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Our Ref: AVS2021-27527/ID
Your Ref: SKG1543B




Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Our Ref: AVS2021-27527/ID

Your Ref: SKG1543B



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Our Ref: AVS2021-27527/ID
Your Ref: SKG1543B




Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Our Ref: AVS2021-27527/ID
Your Ref: SKG1543B




Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Our Ref: AVS2021-27527/ID
Your Ref: SKG1543B




Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Our Ref: AVS2021-27527/ID
Your Ref: SKG1543B



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Our Ref: AVS2021-27527/ID
Your Ref: SKG1543B




Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Our Ref: AVS2021-27527/ID
Your Ref: SKG1543B




Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Our Ref: AVS2021-27527/ID
Your Ref: SKG1543B






Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Our Ref: AVS2021-27527/ID
Your Ref: SKG1543B





Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Our Ref: AVS2021-27527/ID
Your Ref: SKG1543B



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

AJAX

Inspection Services Pte Ltd

Our Ref: AVS2021-27527/ID
Your Ref: SKG1543B



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

918

918 MOTORING PTE LTD

Ang Mo Kio Street 62, #01-07 Link @ AMK, Singapore 569139
Tel: 6479 0918 Fax: 6862 0918

Accident Date:
16/04/2021
Vehicle No.:
SKG1543B

INVOICE NO.:29052021
DATE: 15/07/2021

S/N	Description	Unit Price (\$)	Qty	Total Amount (\$)
1	Lump Sum Accident Repair Costs of V No. SKG1543B	-	-	\$2,400.00
2	Rental for Replacement Vehicle No. SKG1543B From 29/5/2021 to 7/6/2021	\$100.00	2 days	\$200.00
3	Towing From Accident Scene to Workshop.	\$120	1	\$120.00
		TOTAL AMOUNT (SGD)		\$2,720.00

Payment Notes:

All payments must be made only in the form of Cash or Crossed Cheque payable to "918 Motoring Pte Ltd".



918 Motoring Pte Ltd