

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG21010885/UTF3E2

**Date:** 19/11/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7210045271  
**Claimant Vehicle No :** GBE9404J **Insured Vehicle No :** GBL2976J  
Date of Loss: 19/10/2021 Nature of Claim: TP Claim No: 0262006357SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBE9404J**  
Make & Model: NISSAN NV200, 1.5 ABS AIRBAG 2WD 6DR EURO E5 W/RC (M) Engine No: K9KC400D055343  
Reg. Date: 26/04/2016 (Man. Year: 2015) Chassis No: VSKYBAM20Z0123247  
Colour: White Odometer: 131456 km  
Engine Capacity: 1461 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 175/70 R14 Rear Tyre Size: 175/70 R14  
Front Left Side: KAPSEN 6 mm Rear Left Side: Goodyear 6 mm  
Front Right Side: KAPSEN 6 mm Rear Right Side: KAPSEN 6 mm

*The above values represent the remaining tyre tread depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 25/10/2021  
Date Inspected: 25/10/2021 Inspected At: Halland Motor Services (HQ)  
NO 1 KAKI BUKIT AVE 6, #02-24 Autobay @ Kaki Bukit  
Singapore 417883  
Estimated Period of Repair: 15.0 days

**Adjuster:** MARCUS CHUA

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE: \$32,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BACK DOOR O/S	Badly Dented	0.00 F	*- F
2	1		*REAR BACK DOOR 6 PAX STICKER	Necessary	0.00 F	*- F
3	1		*SET REAR BACK DOOR CORPORATE STICKER	Necessary	0.00 F	*- F
4	1		*REAR 70KM/H STICKER	Necessary	0.00 F	*- F
5	3		*REAR EMBLEM	Necessary	0.00 F	*- F
6	1		*REAR FENDER O/S	Badly Dented	0.00 F	*- F
7	1		*REAR FENDER OUTER RAILING O/S	Cut	0.00 F	*- F
8	1		*REAR BACK DOOR N/S	Repair	0.00 F	*- F
9	1		*REAR FENDER INNER TRIM O/S	Torn	0.00 F	*- F
10	1		*REAR TAILLAMP O/S	Broken	0.00 F	*- F
11	1		*REAR END PANEL	Repair	0.00 F	*- F
12	1		*REAR BUMPER	Distorted	0.00 F	*- F
13	2		*REAR BUMPER SIDE HOLDERS	Cracked	0.00 F	*- F
14	1		*SET REAR BUMPER CLIPS	Necessary	0.00 F	*- F
15	1		*REAR AIR VENT	Twisted	0.00 F	*- F
16	1		*REAR FENDER N/S	Badly Dented	0.00 F	*- F
17	1		*REAR FENDER RAILING N/S	Bent	0.00 F	*- F
18	1		*REAR FENDER INNER TRIM N/S	Torn	0.00 F	*- F
19	1		*REAR FENDER AIR VENT N/S	Twisted	0.00 F	*- F
20	1		*TAILLAMP N/S	Cracked	0.00 F	*- F
21	1		*SET REAR FENDER CORPORATE STICKER	Necessary	0.00 F	*- F
22	1		*REAR WHEEL HOUSING PANEL N/S	Repair	0.00 F	*- F
23	2		*REAR WHEEL HUB CAPS	O/S Cut / N/S Missing	0.00 F	*- F
24	1		*REAR WHEEL HUB BEARINGS	Damaged	0.00 F	*- F
25	1		*REAR SHOCK ABSORBER	Twisted	0.00 F	*- F
26	1		*REAR AXLE BEAM	Bent / Twisted	0.00 F	*- F
27	1		*REAR STABILIZER BAR	Bent	0.00 F	*- F
28	1		*REAR STEEL RIM	Bent	0.00 F	*- F
29	1		*REAR TYRE	Cut	0.00 F	*- F
30	1		*REAR WEATHERSTRIP	Serviceable	0.00 F	*- F
31	1		*REAR FENDER OUTER RAILING END O/S	Cut	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)0.000.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >