

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI21010888/R1VF3E2

Date: 15/11/2021

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No: DMPG20008905
Claimant Vehicle No : SHB5248P Insured Vehicle No : SMU1878M
Date of Loss: 21/10/2021 Nature of Claim: TP Claim No: CDMPG21002043

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHB5248P**
Make & Model: TOYOTA PRIUS, 1.5 (A) Engine No: 2ZR1667942
Reg. Date: 19/02/2016 (Man. Year: 2015) Chassis No: JTDKN36UX05767458
Colour: Maroon Odometer: 433435 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Sailun 5 mm Rear Left Side: Sailun 5 mm
Front Right Side: Sailun 5 mm Rear Right Side: Sailun 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,805.88	416.88	4,389.00	91.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,605.00	400.00	1,205.00	75.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,410.88	816.88	5,594.00	87.26
Approved Total (Overridden) (S\$)		800.00		
Nett Amount (S\$)	6,410.88	800.00	5,610.88	87.52

INSPECTION

Date of Assignment: 25/10/2021
Date Inspected: 25/10/2021 Inspected At: SMRT AUTOMOTIVE SERVICES PTE LTD - WOODLANDS (HQ)
60 WOODLANDS INDUSTRIAL PARK E4
Singapore 757705
Estimated Period of Repair: 2.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Nov 2021)
Parts:	144	TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB5248P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
2	10		*BUMPER CLIPS	Not Necessary	21.00 F	*- F
3	1		*BUMPER REINFORCEMENT REAR	Not Necessary	205.70 F	*- F
4	1		*ARM SUB-ASSY, RR BUMPER RH	Not Necessary	139.60 F	*- F
5	1		*ARM SUB-ASSY, RR BUMPER LH	Not Necessary	139.60 F	*- F
6	1		*ANTENNA, ELECTRICAL LOWER REAR	Not Necessary	157.40 F	*- F
7	1		*SENSOR REVERSE	Not Necessary	180.00 F	*- F
8	1		*BUMPER SIDE RETAINER RR/LH	Not Necessary	94.80 F	*- F
9	1		*BUMPER SIDE RETAINER RR/RH	Not Necessary	94.80 F	*- F
10	1		*BUMPER SEAL, RR LH	Not Necessary	88.90 F	*- F
11	1		*BUMPER SEAL, RR RH	Not Necessary	65.70 F	*- F
12	1		*BUMPER LIP COVER RR/LH	Not Necessary	72.20 F	*- F
13	1		*BUMPER LIP COVER RR/RH	Not Necessary	118.10 F	*- F
14	1		*BUMPER LIP REAR	Not Necessary	228.90 F	*- F
15	1		*UNDER COVER SUB-ASSY, RR FLOOR	Not Necessary	514.50 F	*- F
16	1		*UNDER COVER RR SHIELD	Not Necessary	63.90 F	*- F
17	1		*END PANEL	Not Necessary	602.10 F	*- F
18	1		*SEALANT SIKAFLEX	Not Necessary	37.00 F	*- F
19	1		*TAIL LAMP RH	Not Necessary	557.80 F	*- F
20	1		*TAIL LAMP LH	Not Necessary	548.40 F	*- F
21	1		*BUMPER REAR	Repair	458.60 F	*- F
22	1		*ADVERTISEMENT STICKER (SN)	Necessary	296.88 F	*296.88 F

F=Franchise part.

Total Parts (S\$) **4,805.88** **416.88**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING AND BODY WORK	New	507.00	200.00
2	SPRAY PAINT	New	738.00	200.00
3	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	0.00
4	TO REPLACE SUNDRY PARTS	New	100.00	0.00
5	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	0.00
6	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (\$\$)			1,605.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >