

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010889/TVY3N2
Date: 19/04/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00139442000		
Claimant Vehicle No :	SKR3500D	Insured Vehicle No :	SJG6489D		
Date of Loss:	15/10/2021	Nature of Claim:	TP	Claim No:	SNM21D205927/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKR3500D	Engine No:	CDN408232
Make & Model:	AUDI A6, 2.0 (A)	Chassis No:	WAUZZZ4G1EN137822
Reg. Date:	30/01/2015 (Man. Year: 2014)	Odometer:	70917 km
Colour:	Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R17	Rear Tyre Size:	225/55R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	42,643.03	14,159.81	28,483.22	66.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,820.00	2,880.00	4,940.00	63.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	50,463.03	17,039.81	33,423.22	66.23
Approved Total (Overridden) (S\$)		13,600.00		
Nett Amount (S\$)	50,463.03	13,600.00	36,863.03	73.05

INSPECTION

Date of Assignment:	07/11/2021		
Date Inspected:	26/10/2021	Inspected At:	Synergy Building, Kaki Bukit #01-44 Repairer: Tsl Auto Garage
Estimated Period of Repair:	7.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 19 Apr 2022)
Parts: 143	AUDI A6 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKR3500D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER ASSY	Deformed	3,183.80 FL	*2,800.00 FL
2	1		*FRONT BUMPER RIGHT BRACKET	Not Necessary	125.50 FL	*- FL
3	1		*FRONT BUMPER RIGHT RETAINER	Cracked	124.50 FL	*124.50 FL
4	1		*FRONT RIGHT FENDER	Bent	1,156.20 FL	*780.00 FL
5	1		*FRONT RIGHT FENDER INNER COWLING	Not Necessary	425.30 FL	*- FL
6	1		*FRONT RIGHT DOOR PANEL ASSY	Bent	2,458.50 FL	*1,800.00 FL
7	1		*FRONT RIGHT DOOR INNER TRIM BOARD COMPLETE ASSY	Cracked	1,506.20 FL	*1,100.00 FL
8	1		*FRONT RIGHT DOOR LOCK MECHANISM	Bent	371.60 FL	*371.60 FL
9	1		*FRONT RIGHT DOOR LOCK CATCH	Not Necessary	82.80 FL	*- FL
10	1		*FRONT RIGHT DOOR UPPER HINGE	Not Necessary	96.20 FL	*- FL
11	1		*FRONT RIGHT DOOR LOWER HINGE	Not Necessary	88.20 FL	*- FL
12	1		*FRONT RIGHT DOOR WINDOW REGULATOR LINKAGE	Not Necessary	368.30 FL	*- FL
13	1		*FRONT RIGHT DOOR WINDOW REGULATOR MOTOR	Not Necessary	513.20 FL	*- FL
14	1		*FRONT RIGHT DOOR WINDOW DOOR CHROME FRAME	Not Necessary	1,035.60 FL	*- FL
15	1		*FRONT RIGHT DOOR WEATHERSTRIP	Not Necessary	298.30 FL	*- FL
16	1		*FRONT RIGHT DOOR CHECKER LINKAGE	Not Necessary	181.30 FL	*- FL
17	1		*FRONT RIGHT DOOR OUTER HANDLE	Not Necessary	489.10 FL	*- FL
18	1		*FRONT RIGHT WING MIRROR COMPLETE ASSY	Distorted	1,637.80 FL	*1,160.00 FL
19	1		*FRONT RIGHT SUSPENSION DAMPER	Not Necessary	1,153.60 FL	*- FL
20	1		*FRONT RIGHT KNUCKLE ARM	Not Necessary	1,228.60 FL	*- FL
21	1		*FRONT RIGHT WHEEL HUB BEARING	Not Necessary	388.70 FL	*- FL
22	1		*FRONT RIGHT LOWER CONTROL ARM	Not Necessary	1,134.80 FL	*- FL
23	1		*FRONT RIGHT UPPER LINK	Not Necessary	588.60 FL	*- FL
24	1		*FRONT RIGHT LOWER LINK	Not Necessary	576.80 FL	*- FL
25	1		*FRONT RIGHT UPPER CONTROL ARM	Not Necessary	1,167.80 FL	*- FL
26	1		*FRONT RIGHT B PILLAR	Not Necessary	1,643.50 FL	*- FL
27	1		*FRONT HEADLAMP RH (HID)	Cracked	3,880.00 FL	*2,100.00 FL
28	1		*REAR BUMPER ASSY	Repair	2,998.30 FL	*- FL
29	1		*REAR BUMPER RIGHT BRACKET	Not Necessary	118.30 FL	*- FL
30	1		*REAR BUMPER RIGHT SIDE RETAINER	Not Necessary	186.30 FL	*- FL
31	1		*REAR RIGHT FENDER ASSY	Repair	2,356.20 FL	*- FL
32	1		*REAR RIGHT FENDER INNER COWLING	Not Necessary	425.30 FL	*- FL
33	1		*REAR RIGHT DOOR PANEL ASSY	Bent	2,023.30 FL	*2,023.30 FL
34	1		*REAR RIGHT DOOR OUTER HANDLE	Not Necessary	489.10 FL	*- FL
35	1		*REAR RIGHT DOOR LOCK MECHANISM	Not Necessary	372.60 FL	*- FL
36	1		*REAR RIGHT DOOR LOCK CATCH	Not Necessary	82.80 FL	*- FL
37	1		*REAR RIGHT DOOR UPPER HINGE	Not Necessary	96.30 FL	*- FL
38	1		*REAR RIGHT DOOR LOWER HINGE	Not Necessary	88.20 FL	*- FL
39	1		*REAR RIGHT DOOR WINDOW REGULATOR LINKAGE	Not Necessary	368.30 FL	*- FL
40	1		*REAR RIGHT DOOR WINDOW REGULATOR MOTOR	Not Necessary	513.20 FL	*- FL
41	1		*REAR RIGHT DOOR WINDOW DOOR CHROME FRAME	Not Necessary	935.60 FL	*- FL
42	1		*REAR RIGHT DOOR CHECKER LINKAGE	Not Necessary	181.30 FL	*- FL
43	1		*REAR RIGHT DOOR INNER TRIM BOARD COMPLETE ASSY	Not Necessary	1,206.20 FL	*- FL
44	1		*REAR RIGHT DOOR WEATHERSTRIP	Cut	298.30 FL	*298.30 FL
45	1		*REAR RIGHT TAILLAMP	Not Necessary	767.90 FL	*- FL
46	1		*REAR WINDSCREEN GLASS MOULDING	Not Necessary	288.80 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR RIGHT QUARTER GLASS MOULDING	Not Necessary	186.30 FL	*- FL
48	12		*FRONT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
49	1		*FRONT RIGHT SPORTS RIM	Cut	1,250.00 FS	*1,000.00 FS
50	1		*FRONT RIGHT TYRE	Not Necessary	600.00 FS	*- FS
51	1		*FRONT NO PLATE WITH GARNISH	Not Necessary	100.00 FS	*- FS
52	4		*FRONT RIGHT FENDER COWLING CLIPS	Not Necessary	30.00 FS	*- FS
53	10		*FRONT RIGHT DOOR INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
54	1		*FRONT RIGHT B PILLAR SEALANT	Not Necessary	100.00 FS	*- FS
55	1		*FRONT RIGHT DOOR STICKER	Necessary	150.00 FS	*100.00 FS
56	1		*FRONT RIGHT DOOR FENDER STICKER	Necessary	150.00 FS	*100.00 FS
57	12		*REAR BUMPER CLIPS	Not Necessary	60.00 FS	*- FS
58	1		*REAR RIGHT SPORT RIM	Cut	1,250.00 FS	*1,000.00 FS
59	1		*REAR RIGHT TYRE	Not Necessary	600.00 FS	*- FS
60	1		*REAR RIGHT FENDER SEALANT	Not Necessary	100.00 FS	*- FS
61	6		*REAR RIGHT FENDER INNER COWLING CLIPS	Not Necessary	30.00 FS	*- FS
62	1		*REAR RIGHT QUARTER GLASS SEALANT	Not Necessary	80.00 FS	*- FS
63	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	100.00 FS	*- FS
64	8		*REAR RIGHT DOOR INNER TRIM BOARD CLIPS	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	44,637.40	14,787.70
- List Item Discount on L Items 5.00/5.00% (\$)	1,994.37	627.89
Total Parts (\$)	42,643.03	14,159.81

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN FRONT RIGHT AFFECTED AREA AND REPLACE FRONT RIGHT DAMAGED PARTS	New	1,400.00	600.00
2	TO PUTTY AND SPRAY PAINTING FRONT RIGHT PORTION	New	1,400.00	600.00
3	TO APPLY ANTI RUST PROOFING TO FRONT RIGHT AFFECTED AREA	New	140.00	30.00
4	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN REAR RIGHT AFFECTED AREA AND REPLACE REAR RIGHT DAMAGED PARTS	New	1,400.00	600.00
5	TO PUTTY AND SPRAY PAINTING REAR RIGHT PORTION	New	1,400.00	600.00
6	TO CHECK REAR LIGHTING AND WIRING	New	50.00	30.00
7	TO REMOVE AND INSTALL REAR FUEL TANK TO FACILITATE THE REPAIR	New	180.00	0.00
8	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR	New	140.00	60.00
9	TO APPLY ANTI RUST PROOFING TO REAR RIGHT AFFECTED AREA	New	140.00	40.00
10	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR	New	140.00	0.00
11	TO REMOVE AND INSTALL REAR RIGHT QUARTER GLASS	New	80.00	0.00
12	TO REMOVE AND INSTALL FRONT RIGHT UNDERCARRIAGE PARTS	New	350.00	0.00
13	TO BALANCE FRONT RIGHT WHEEL	New	50.00	30.00
14	TO BALANCE REAR RIGHT WHEEL	New	50.00	30.00
15	TO CONDUCT WHEEL ALIGNMENT	New	120.00	80.00
16	TO SYNCHRONISE FRONT RIGHT WING MIRROR FOR FUNCTION	New	120.00	30.00
17	TO REMOVE AND INSTALL FRONT RIGHT DOOR LOCK MECHANISM	New	80.00	60.00
18	TO REMOVE AND INSTALL REAR RIGHT DOOR LOCK MECHANISM	New	80.00	60.00
19	TO CHECK FRONT RIGHT AND REAR RIGHT DOOR CENTRAL LOCKING FOR FUNCTION	New	80.00	30.00
20	TO TRANSFER FRONT RIGHT DOOR GLASS TO NEW DOOR	New	80.00	0.00
21	TO TRANSFER REAR RIGHT DOOR GLASS TO NEW DOOR	New	80.00	0.00
22	TO REMOVE AND INSTALL FRONT RIGHT DOOR REGULATOR WITH MOTOR ASSY	New	80.00	0.00
23	TO REMOVE AND INSTALL REAR RIGHT DOOR REGULATOR WITH MOTOR ASSY	New	80.00	0.00
24	TOWING SERVICE	New	100.00	0.00
Gross Labour Cost (\$)			7,820.00	2,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >