

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG21010890/AUF3N2
Date: 26/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800028890
Claimant Vehicle No :	GBF2065U	Insured Vehicle No :	GBH9900C
Date of Loss:	20/10/2021	Nature of Claim:	TP
		Claim No:	2075813676SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF2065U		
Make & Model:	NISSAN NV350, 2.5 PANEL VAN 5MT 5DR EURO V (M)	Engine No:	YD25392446A
Reg. Date:	29/07/2016 (Man. Year: 2016)	Chassis No:	JN1MC2E26Z0006333
Colour:	Silver	Odometer:	117651 km
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	195R15
Front Left Side:	OHTSU 6 mm	Rear Left Side:	OHTSU 6 mm
Front Right Side:	OHTSU 6 mm	Rear Right Side:	OHTSU 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,797.07	4,309.67	3,487.40	44.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,980.00	1,720.00	1,260.00	42.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,777.07	6,029.67	4,747.40	44.05
Approved Total (Overridden) (S\$)		4,800.00		
Nett Amount (S\$)	10,777.07	4,800.00	5,977.07	55.46

INSPECTION

Date of Assignment:	25/10/2021		
Date Inspected:	26/10/2021	Inspected At:	Cheng Motor Work Company (HQ) NO.1 KAKI BUKIT AVE 6 #01-83 Singapore 417883
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING**Manager:** Tan Hui Zhen*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTH LID	Dented	1,998.30 FN	*1,816.00 FN
2	1		*BOOTH LID RUBBER	Cut	134.30 FN	*134.30 FN
3	1		*EMBLEM NV350 URVAN	Necessary	110.00 FN	*110.00 FN
4	1		*BOOTH LID LOGO	Necessary	64.90 FN	*64.90 FN
5	2		*BOOTH LID SIDE LOCK	Not Necessary	395.60 FN	*- FN
6	2		*BOOTH LID SIDE LOCK CAP	Not Necessary	43.00 FN	*- FN
7	2		*BOOTH LID SIDE LOCK STOPPER	Not Necessary	20.40 FN	*- FN
8	2		*BOOTH LID ABSORBER	Not Necessary	478.30 FN	*- FN
9	2		*NUMBER PLATE LAMP	Not Necessary	188.20 FN	*- FN
10	1		*BOOTH LID INNER LOCK	Damaged	287.10 FN	*287.10 FN
11	1		*BOOTH LID LOWER LOCK	Not Necessary	198.30 FN	*- FN
12	1		*BOOTH LID CENTER CHROME	Cracked	613.70 FN	*449.00 FN
13	1		*BOOTH LID KEY LOCK	Not Necessary	85.20 FN	*- FN
14	1		*BOOTH LID INNER TRIM BOARD	Not Necessary	226.80 FN	*- FN
15	1		*REAR BUMPER	Deformed	667.20 FN	*667.20 FN
16	2		*SET BUMPER SIDE RETAINER	Necessary	131.00 FN	*131.00 FN
17	1		*REAR BUMPER CENTER STEP PANEL	Dented	208.00 FN	*208.00 FN
18	1		*SET REAR BUMPER CLIP	Necessary	65.00 FN	*30.00 FN
19	1		*REAR END PANEL OUTER	Dented	174.10 FN	*174.10 FN
20	1		*REAR END PANEL INNER PANEL	Repair	494.15 FN	*- FN
21	1		*END PANEL TOP CHROME	Bent	147.40 FN	*147.40 FN
22	1		*TAIL LAMP L/H	Cracked	247.30 FN	*247.30 FN
23	1		*TAIL LAMP R/H	Not Necessary	247.30 FN	*- FN
24	1		*REAR EXHAUST PIPE	Not Necessary	934.70 FN	*- FN
25	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	36.50 FN	*- FN
26	1		*70KM STICKER	Necessary	20.00 FS	*15.00 FS
27	1		*8 PAX STICKER	Necessary	20.00 FS	*15.00 FS
28	1		*WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
29	1		*REAR NUMBER PLATE	Not Necessary	40.00 FS	*- FS
30	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$)	8,616.75	4,756.30
- Nett Item Discount on N Items 10.00/10.00% (\$)	819.68	446.63
Total Parts (\$)	7,797.07	4,309.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRE	New	60.00	30.00
2	TO REMOVE/RENEW REVERSE SENSOR	New	100.00	50.00
3	TO REMOVE/REFIT REAR WINDSCREEN GLASS	New	150.00	120.00
4	TO REMOVE/TRANSFER BOOTH LID MECHANICAL	New	150.00	60.00
5	TO APPLY RUST-PROOFING	New	200.00	60.00
6	TO REMOVE/RENEW EXHAUST SILENCER BOX	New	120.00	0.00
7	TO KNOCKING,WELDING,CUTTING,REPAIRER AND REPLACED OF PARTS	New	1,000.00	700.00
8	TO SPRAY PAINT ON THE DAMAGE PORTION	New	1,200.00	700.00
			Gross Labour Cost (\$\$)	2,980.00
				1,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >