

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG121010894/UTF3N2**Date:** 10/11/2021REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : GBF9562E**Insured Vehicle No :** YQ3064K

Date of Loss: 20/10/2021

Nature of Claim:

TP

Claim No: CDMCG21002035

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBF9562E**

Make & Model: MITSUBISHI CANTER, 3.0 D FEA01BR2SDEB (CBU) (M)

Engine No: 4P10C48613

Reg. Date: 28/04/2017 (Man. Year: 2016)

Chassis No: FEA01BA20580

Colour: White

Odometer: 182493 km

Engine Capacity: 2998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15

Rear Tyre Size: 195R15(D)

Front Left Side: Triangle 6 mm

Rear Left Side: Triangle 6/6 mm

Front Right Side: Triangle 6 mm

Rear Right Side: Triangle 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,070.90	9,353.59	14,717.31	61.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,600.00	3,180.00	1,420.00	30.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,670.90	12,533.59	16,137.31	56.28
Approved Total (Overridden) (S\$)		10,000.00		
Nett Amount (S\$)	28,670.90	10,000.00	18,670.90	65.12

INSPECTION

Date of Assignment: 25/10/2021

Date Inspected: 25/10/2021 Inspected At:

Liu's Brother Auto Workshop (HQ)

1 Kaki Bukit Ave 6 #01-01, Auto Bay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 10.0 days

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 10 Nov 2021)		
Parts:	N/A	MITSUBISHI CANTER 3.0 D FEA01BR2SDEB (CBU) (M) (Model not available in database)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for GBF9562E)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Distorted	1,127.60 F	*780.90 FL
2	1	*FRONT BUMPER BRACKET	O/s Bent	592.60 F	*296.30 FL
3	1	*FRONT BUMPER SIDE	O/s Distorted	883.40 F	*319.82 FL
4	1	*FRONT BUMPER FRONT RADAR SENSOR	Not fitted	2,729.80 F	*- FL
5	1	*FRONT BUMPER FRONT RADAR SENSOR COVER	Not fitted	168.90 F	*- FL
6	1	*FRONT HEAD LAMP	O/s Broken/N/s Not Necessary	1,712.80 F	*492.21 FL
7	1	*FRONT SIDE LAMP O/S	Broken	213.80 F	*213.80 FL
8	1	*FRONT SIGNAL LAMP	O/s Broken/N/s Not Necessary	648.60 F	*208.21 FL
9	1	*SET FRONT GRILLE CLIPS	Necessary	80.00 F	*35.00 FL
10	1	*FRONT GRILLE }	Cracked	1,043.00 F	*785.21 FL
11	1	*FRONT MITSUBISHI LOGO MOTIF }		186.80 F	*- FL
12	1	*FRONT CORNER PANEL RH	Repair	486.90 F	*- FL
13	1	*FRONT WIPER PANEL	Cracked	1,482.10 F	*589.23 FL
14	1	*FRONT STEP GARNISH RH	Cracked	623.00 F	*341.21 FL
15	1	*FRONT PANEL	Badly Dented	2,436.60 F	*1,660.58 FL
16	1	*FRONT AIRCON COOLING COIL UNIT	Cracked	3,591.70 F	*2,823.15 FL
17	1	*REAR TAIL LAMP RH	Cracked	244.30 F	*208.50 FL
18	1	*REAR TAIL LAMP PANEL	Not Necessary	217.00 F	*- FL
19	1	*REAR NUMBER PLATE LAMP	Not Necessary	197.00 F	*- FL
20	2	*SET FRONT BUMPER SIDE CLIPS	Not Necessary	130.00 FS	*- FS
21	1	*FRONT NUMBER PLATE (METAL)	Bent	28.00 FS	*14.00 FS
22	1	*SET FRONT CORNER PANEL CLIPS	Not Necessary	28.00 FS	*- FS
23	2	*REAR CARGO BOX REAR DOOR	Dented/Bent	4,003.00 FS	*2,400.00 FS
24	2	*REAR CARGO BOX BAR LOCK	Bent	440.00 FS	*360.00 FS
25	4	*REAR CARGO BOX TAILGATE HINGES	Not Necessary	748.00 FS	*- FS
26	1	*REAR NUMBER PLATE (METAL)	Bent	28.00 FS	*14.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	24,070.90	11,542.12
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	2,188.53
Total Parts (\$\$)	24,070.90	9,353.59

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REINSTALL DASHBOARD,METER INSTRUMENTS,DISCONNECT WIRING & ETCS	New	400.00	250.00
2	TO REMOVE & REFIX AIR CON,RE-FILL AIR CON GAS & TEST FOR LEAKAGES	New	400.00	100.00
3	TO REMOVE,REPLACE AND TRANSFER CARGO BOX AND REPAIR CHASSIS	New	1,000.00	400.00
4	LABOR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS ETCS	New	1,200.00	1,080.00
5	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREA	New	1,500.00	1,300.00
6	TO APPLY RUST PROOFING,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	100.00	50.00
Gross Labour Cost (S\$)			4,600.00	3,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >