


ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: GBF9562E
at Workshop m/s 1145 30
of _____
Insured: YQ3064K
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 481.
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: 10 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA \$25087
Vehicle: IN / OUT

Date: _____ Person Contacted: 2079K.

Veh No: GBF9562E Yr Regn: 28/4/17
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CMV
Make: Mif counter FEA00c 2998
Colour: white A/C: Insured / Std / NI / NA
Sp. Reading 182493 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: FEA01BA20580
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 195 R15
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Triangle
Front 6 mm Rear 6/6 mm
R/Bal. 6 mm L/Bal. 6/6 mm
D.O.A. 20/10/14 D.O.I. 25/10/14
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear & Pity.
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
20/11/14 22913

8/11/14 L/S \$10,000 confirmed with Susan.
red: 18670.90;65%

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 10

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$) \$ + RS. \$
☐ : Interview (\$) Photos
☐ : Tech. Invs (\$) Others
☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 5329793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBF9562E211020

Estimate**Customer****Name:** ERGO Insurance Pte Ltd**Address:** Motor Claims Department

8 Temasek Boulevard #04-01

Suntec Tower Three

Singapore 038988

Date:

22-10-21

Vehicle No:

GBF9562E

Model/Make: Mitsubishi Canter

FEA01BR2SDEB (CBU)

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Bumper 215 789.80	\$ 1,127.60	
2	Bumper Bracket 02 pcs (@ S\$296.30) 01580M	\$ 592.60	
3	Bumper Side 02 pcs (@ S\$441.70) 215 2.5 319.82	\$ 883.40	
4	Bumper Side Clips 02 set (@ S\$65.00 SN) 11	\$ 130.00	SN X
5	Number Plate (Metal) Bent	\$ 28.00	SN 14 5/11
6	Bumper Front 'Radar' Sensor NF	\$ 2,729.80	X
7	Bumper Front 'Radar' Sensor Cover NF	\$ 168.90	X
8	Head Lamp 02 pcs (@ S\$856.40) NLSA1 015820	\$ 1,712.80	1 PC 492.21
9	Side Lamp 015 B20	\$ 213.80	
10	Signal Lamp 02 pcs (@ S\$324.30) NLSA1 015820	\$ 648.60	1 PC 208.21
11	Grille CNE 784.21	\$ 1,043.00	
12	Grille Clips 1 set 35.00	\$ 80.00	
13	"Mitsubishi Logo" Motif C/W grille	\$ 186.80	X
14	Corner Panel Rh R	\$ 486.90	X
15	Corner Panel clips 1 set 11	\$ 28.00	SN X
16	Wiper Panel CNE 589.23 (25%)	\$ 1,482.10	
17	Step Garnish Rh CNE 341.21	\$ 623.00	
18	Panel Body 1660.58	\$ 2,436.60	
19	Aircon Cooling Coil Unit CNO 2823.15	\$ 3,591.70	
20	Rear Cargo Box Rear Door 02 pcs (@ S\$2,001.50) 20/201	\$ 4,003.00	SN 2400 5/11
21	Cargo Box Bar Lock 02 pcs (@ S\$220.00 SN) Bent 1802	\$ 440.00	SN 360 5/11
22	Cargo Box Tailgate Hinges 04 pcs (@ S\$187.00) 11	\$ 748.00	SN X
23	Tail Lamp Rh CNE 208.50	\$ 244.30	X
24	Tail Lamp Panel 11	\$ 217.00	X
25	Number Plate Lamp 11	\$ 197.00	X
26	Number Plate (Metal) Bent	\$ 28.00	SN 14 5/11
	Remove & reinstall dashboard, meter instruments, disconnect wiring & Etc	\$ 400.00	- 250
	To remove & refix air con, re-fill air con gas & test for leakages	\$ 400.00	- 100
	To remove, replace and transfer Cargo Box and repair chassis	\$ 1,000.00	- 400
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,200.00	- 1080
	To putty & spray painting & including touch up paint on accident affected area	\$ 1,500.00	- 1300
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 100.00	- 50

Total Parts & Labour of estimate for damaged vehicle

\$ 28,670.90

Total amount in Lump Sum Basis for repaired vehicle**SDLS:**

- To resurvey before and after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and
- subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



M/s Liu's Brother Auto Engrg Wks

P-8754-12
252

P-6565-59

S.N-2788

L-3180

12833349

N/A Parted
24.11

4/5 \$10,000

25/10/21

The other 1200
10 days.